

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 2
SECTION B**

Construction debris and trash scattered around the building. Contractor to cleanup.

PHOTOGRAPH #2



**BUILDING 2
SECTION E**

Construction debris and trash scattered around the building. Contractor to cleanup.

PHOTOGRAPH #3



**BUILDING 2
SECTION H**

Construction debris and trash scattered around the building. Contractor to cleanup.

PHOTOGRAPH #4



**BUILDING 2
SECTION D**

Construction debris and trash scattered around the building. Contractor to cleanup.

PHOTOGRAPH #5



**BUILDING 3
SECTION G**

Contractor installed new plywood soffit with vent. All seams were caulked and ready for paint.

PHOTOGRAPH #6



**BUILDING 3
SECTION H**

Contractor made corrections where seam tape was improperly used at penetrations.

PHOTOGRAPH #7



**BUILDING 3
SECTION H**

Contractor made corrections where seam tape was improperly used at penetrations.

PHOTOGRAPH #8



**BUILDING 3
SECTION H**

Contractor installed new plywood soffit. All seams were caulked and ready for paint.

PHOTOGRAPH #9



**BUILDING 3
SECTION A**

Simpson Strong Tie connectors and straps installed as per drawings and specifications.

PHOTOGRAPH #10



**BUILDING 3
SECTION A**

Simpson Strong Tie connectors and straps installed as per drawings and specifications.

PHOTOGRAPH #11



**BUILDING 3
SECTION B**

Simpson Strong Tie connectors and anchors installed as per drawings and specifications.

PHOTOGRAPH #12



**BUILDING 3
SECTION B**

Trusses are missing Strap 'G', located from truss to double top plate.

PHOTOGRAPH #13



**BUILDING 3
SECTION C**

Simpson Strong Tie connectors and anchors installed as per drawings and specifications.

PHOTOGRAPH #14



**BUILDING 3
SECTION C**

Simpson Strong Tie connectors and straps installed as per drawings and specifications.

PHOTOGRAPH #15



**BUILDING 3
SECTION C**

Contractor applied Copper-Green Wood Preservative to bottom 2'-0" of framing.

PHOTOGRAPH #16



**BUILDING 3
SECTION C**

Contractor applied Copper-Green Wood Preservative to bottom 2'-0" of framing.

PHOTOGRAPH #17



**BUILDING 3
SECTION D**

Simpson Strong Tie connectors and anchors installed as per drawings and specifications.

PHOTOGRAPH #18



**BUILDING 3
SECTION D**

Simpson Strong Tie connectors and straps installed as per drawings and specifications.

PHOTOGRAPH #19



**BUILDING 6
SECTION E**

Wood rot damage marked for repairs at stud framing and around windows.

PHOTOGRAPH #20



**BUILDING 6
SECTION F**

Header above windows marked for replacement due to wood rot.

PHOTOGRAPH #21



**BUILDING 6
SECTION F**

Wood rot damage marked for repairs below windows.

PHOTOGRAPH #22



**BUILDING 6
SECTION G**

Stud framing at balcony corner marked for repairs.

PHOTOGRAPH #23



**BUILDING 6
SECTION G**

Wood rot damage marked for repairs below windows.

PHOTOGRAPH #24



**BUILDING 6
SECTION H**

Roof truss wood rot marked for replacement.

PHOTOGRAPH #25



**BUILDING 6
SECTION H**

Roofing sheathing damage and recent roofing leaks observed over soffit area. Owners to have roofing contractor perform repair.