

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 18
UNIT #1824 BALCONY**

Top rails have been fastened to stucco walls.

PHOTOGRAPH #2



**BUILDING 18
UNIT #1824 BALCONY**

Re-installation of downspout and cleanup of grounds will have been completed.

PHOTOGRAPH #3



**BUILDING 18
UNIT #1824 BALCONY**

Bronze caulking has been completed at stucco to screen enclosure.

PHOTOGRAPH #4



**BUILDING 7
UNIT #727 BALCONY**

Top rail fastening angle has been moved as required and paint touched up.

PHOTOGRAPH #5



BUILDING 25

Roof tiles have been re-installed with foam at new kick out flashing.

PHOTOGRAPH #6



BUILDING 25

Roof tiles have been re-installed with foam at new kick out flashing.