


PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 24
SECTION B**

Hose bib has been sealed at stucco.

PHOTOGRAPH #2



**BUILDING 24
SECTION D**

Utility boxes have been touched up with matching paint.

PHOTOGRAPH #3



**BUILDING 24
SECTION A- BREEZWAY**

Void in stucco has been repaired and re-painted.

PHOTOGRAPH #4



**BUILDING 24
BREEZWAY AT UNIT #2427**

Hole under light fixture has been filled and re-painted.

PHOTOGRAPH #5



**BUILDING 26
SECTION E**

Stucco sub-contractor has installed JumboTex WRB, stucco accessories and lath in preparation for stucco application.

PHOTOGRAPH #6



**BUILDING 26
SECTION E BREEZWAY**

Stucco sub-contractor has installed JumboTex WRB, stucco accessories and lath in preparation for stucco application.

PHOTOGRAPH #7



**BUILDING 26
SECTION E AND F**

Grounds below and around scaffolding is not fenced off as planned. Clean up of site is not acceptable or in accordance with contract document requirements.

PHOTOGRAPH #8



**BUILDING 27
SECTION H**

Gable end wall framing has been sprayed with Bora-Care termite treatment in preparation for installation of sheathing.

PHOTOGRAPH #9



**BUILDING 27
SECTION G**

Grounds below and around scaffolding is not fenced off as planned.

PHOTOGRAPH #10



**BUILDING 27
SECTION G**

Contractor has installed construction fencing below scaffolding work areas.

PHOTOGRAPH #11



**BUILDING 27
ATTIC #2724**

Contractor has made gusset repairs, scab repairs and fire wall repairs.

PHOTOGRAPH #12



**BUILDING 27
ATTIC #2724**

Contractor has made gusset repairs, scab repairs and fire wall repairs.

PHOTOGRAPH #13



**BUILDING 27
ATTIC # 2723**

Contractor has made gusset repairs, scab repairs and fire wall repairs.

PHOTOGRAPH #14



**BUILDING 27
ATTIC # 2723**

Contractor has made gusset repairs, scab repairs and fire wall repairs.

PHOTOGRAPH #15



**BUILDING 27
ATTIC # 2726**

Contractor has made gusset repairs, scab repairs and fire wall repairs.