

### PHOTOGRAPHS

PHOTOGRAPH #1



#### BUILDING 26 SECTION E

Florida Paints TropiCrete concrete sealer has been applied to ground level walkways.

PHOTOGRAPH #2



#### BUILDING 26 SECTION E

Florida Paints TropiCrete concrete sealer has been applied to ground level walkways.

**PHOTOGRAPH #3**



**BUILDING 26  
SECTION F**

Simpson #HSLQ37-SDS2.5 shear clip required at this C2 Balcony has not yet been installed.

**PHOTOGRAPH #4**



**BUILDING 26  
SECTION F**

Simpson HGA10KT shear clip required at this C1A Balcony has not yet been installed.

**PHOTOGRAPH #5**



**BUILDING 26  
SECTION F**

Balcony railings have been installed but top railing anchors have not yet been attached to columns.

**PHOTOGRAPH #6**



**BUILDING 26  
SECTION B**

Finish paint is peeling off new dryer vents.

**PHOTOGRAPH #7**



**BUILDING 26  
UNIT #2616**

Drywall has been repaired at interior side where damaged.

**PHOTOGRAPH #8**



**BUILDING 26  
UNIT #2616**

Contractor has cleaned area of spilled paint at owners' tiles.


**PHOTOGRAPH #9**



**BUILDING 27  
SECTION F**

Stucco sub-contractor continuing to apply new lathing and stucco accessories.

**PHOTOGRAPH #10**



**BUILDING 27  
SECTION F**

Metal lathing now being applied is the originally submitted and approved product.

**PHOTOGRAPH #11**



**BUILDING 27  
SECTION F**

Contractor is installing new soffit wood with vented soffit screen.

**PHOTOGRAPH #12**



**BUILDING 27  
SECTION F**

Newly installed soffit wood appears to be stained from roof leaks.


**PHOTOGRAPH #13**



**BUILDING 27  
SECTION E**

Pre-existing roof leaking and damaged roof sheathing is to be repaired by owners roofing contractors.

**PHOTOGRAPH #14**



**BUILDING 27  
SECTION D**

Tyvek WRB checked for overlapping and taping of seams.

**PHOTOGRAPH #15**



**BUILDING 27  
SECTION D**

Window fin nailing and Dupont flashings checked at newly installed PGT windows.

**PHOTOGRAPH #16**



**BUILDING 27  
SECTION C**

Contractor has performed framing repairs and strapping.

**PHOTOGRAPH #17**



**BUILDING 27  
SECTION B**

Damaged framing being marked for repairs.

**PHOTOGRAPH #18**



**BUILDING 27  
SECTION B**

Damaged framing being marked for repairs.

**PHOTOGRAPH #19**



**BUILDINGS 27  
SECTION B**

Contractor has performed repairs at damaged C1A type balcony.

**PHOTOGRAPH #20**



**BUILDINGS 27  
SECTION B**

Contractor has poured new concrete pedestal for breezeway column.

**PHOTOGRAPH #21**



**BUILDINGS 27  
SECTION A**

Construction fencing has not been provided.