

**PHOTOGRAPHS**

**PHOTOGRAPH #1**



**BUILDING 27  
SECTION F**

Contractor has installed sealants at balcony deck kick out flashing transitions.

**PHOTOGRAPH #2**



**BUILDING 27  
SECTION F**

Contractor has installed sealants at balcony deck kick out flashing transitions.

**PHOTOGRAPH #3**



**BUILDING 27  
SECTION F**

Contractor has installed sealants at balcony deck kick out flashing transitions.

**PHOTOGRAPH #4**



**BUILDING 27  
SECTION G**

Contractor has installed sealants at balcony deck kick out flashing transitions.

**PHOTOGRAPH #5**



**BUILDING 27  
SECTION E**

Florida Paint representative performed PH tests at new stucco for approval to proceed with paint application.

**PHOTOGRAPH #6**



**BUILDING 27  
SECTION D**

Florida Paint representative performed PH tests at new stucco for approval to proceed with paint application.

**PHOTOGRAPH #7**



**BUILDING 27  
SECTION D**

Contractor has primed and painted new stucco.


**PHOTOGRAPH #8**



**BUILDING 27  
SECTION B**

Sub-contractor in process of applying stucco lath and stucco accessories.


**PHOTOGRAPH #9**



**BUILDING 27  
SECTION B**

Fasteners not fully embedded at lath,  
marked for correction.

**PHOTOGRAPH #10**



**BUILDING 27  
SECTION B**

Sub-contractor made corrections to  
fasteners not fully embedded at lath.

**PHOTOGRAPH #11**



**BUILDING 27  
SECTION B**

Sub -contractor made corrections at lath overlapping where it was not connected with tie wire.

**PHOTOGRAPH #12**



**BUILDING 27  
SECTION B**

Contractor fencing not in place.

**PHOTOGRAPH #13**



**BUILDING 27  
SECTION A-BREEZWAY**

Contractor has finish painted front doors.

**PHOTOGRAPH #14**



**BUILDING 27  
SECTION A**

Contractor has installed Tyvek HomeWrap, DuPont flashings and new PGT windows.

**PHOTOGRAPH #15**



**BUILDING 10  
SECTION F – UNIT #1024**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #16**



**BUILDING 10  
SECTION F – UNIT #1024**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #17**



**BUILDING 10  
SECTION D – UNIT #1028**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #18**



**BUILDING 10  
SECTION D – UNIT #1028**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #19**



**BUILDING 10  
SECTION D – UNIT #1027**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #20**



**BUILDING 10  
SECTION D – UNIT #1027**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #21**



**BUILDING 10  
SECTION B – UNIT #1025**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #22**



**BUILDING 10  
SECTION B – UNIT #1025**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #23**



**BUILDING 10  
SECTION B – UNIT #1026**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #24**



**BUILDING 10  
SECTION B – UNIT #1026**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #25**



**BUILDING 10  
SECTION F – UNIT #1023**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #26**



**BUILDING 10  
SECTION F – UNIT #1023**

Attic framing and firewall repairs reviewed and quantified with Contractor.

**PHOTOGRAPH #27**



**BUILDING 10  
SECTION D**

Contractor has performed repairs at framing studs, top plates, sub floor and window headers.

**PHOTOGRAPH #28**



**BUILDING 10  
SECTION D**

Contractor has performed repairs at framing studs, top plates, sub floor and window headers

**PHOTOGRAPH #29**



**BUILDING 10  
SECTION D**

Simpson Strong – Tie, 10d 1 ½ " nails used for fastening connector straps.

**PHOTOGRAPH #30**



**BUILDING 10  
SECTION E**

Contractor has performed repairs at framing studs, and bottom plate.