

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 27 SECTION F

Contractor has loaded re-painted rails onto decks for installation.

PHOTOGRAPH #2



BUILDING 27 SECTION F

Unit #2718- Simpson Strong -Tie shear clip and screws have not been installed at built up rail beam.


PHOTOGRAPH #3



**BUILDING 27
SECTION F**

Contractor has removed and replaced several window perimeter sealants were adhesion concerns are present.

PHOTOGRAPH #4



**BUILDING 27
SECTION D**

Stucco and construction debris on A/C equipment.

PHOTOGRAPH #5



**BUILDING 27
SECTION B**

Stucco sub-contractor applying scratch and brown coats.

PHOTOGRAPH #6



**BUILDING 27
SECTION B**

Stucco sub-contractor applying scratch and brown coats.

PHOTOGRAPH #7



**BUILDING 27
SECTION B**

Sub-contractor applying Broco stucco cement.

PHOTOGRAPH #8



**BUILDING 10
SECTION D**

Termite control company has applied Bora-Care termite treatment.

PHOTOGRAPH #9



**BUILDING 10
SECTION D**

Contractor has not removed and replaced damaged framing at windows edge.

PHOTOGRAPH #10



**BUILDING 10
SECTION D**

Unit #1018- drywall damage exposed when sheathing and insulation removed. Vintage Grand management notified of required repairs not included in current scope of contractor's repairs.

PHOTOGRAPH #11



**BUILDING 10
SECTION D**

Unit #1018- drywall damage exposed when sheathing and insulation removed. Vintage Grand management notified of required repairs not included in current scope of contractor's repairs.

PHOTOGRAPH #12



**BUILDING 10
SECTION D**

Unit #1018- drywall damage exposed when sheathing and insulation removed. Vintage Grand management notified of required repairs not included in current scope of contractor's repairs.

PHOTOGRAPH #13



**BUILDING 10
SECTION E**

Roof sheathing leak damage not covered in scope of repairs.

PHOTOGRAPH #14



**BUILDING 10
SECTION E**

Contractor has installed Simpson Strong-Tie strap connectors at framing.

PHOTOGRAPH #15



**BUILDING 10
SECTION E**

Framing repairs and new Simpson Strong-Tie connectors being installed at breezeway area.

PHOTOGRAPH #16



**BUILDING 10
SECTION F**

Framing repairs reviewed and quantified with contractor.

PHOTOGRAPH #17



**BUILDING 10
SECTION F**

Framing repairs reviewed and quantified with contractor.

PHOTOGRAPH #18



**BUILDING 10
SECTION F**

Unit #1024 -framing repairs in progress as directed by ESI #1.

PHOTOGRAPH #19



**BUILDING 10
SECTION G**

Roof sheathing leak damage not covered
in scope of repairs.

PHOTOGRAPH #20



**BUILDING 10
SECTION G – BREEZWAY**

Contractor rebuilding damaged
breezeway framing.

PHOTOGRAPH #21



**BUILDING 10
SECTION G**

Framing repairs reviewed and quantified with contractor.