

PHOTOGRAPHS


PHOTOGRAPH #1



BUILDING 27 SECTION D

Stucco sub-contractor applying scratch coat of stucco.

PHOTOGRAPH #2



BUILDING 27 SECTION C

Florida Paints Two Part Aliphatic Urethane Enamel finish being applied to railings.

PHOTOGRAPH #3



**BUILDING 27
SECTION C**

Florida Paints Two Part Aliphatic Urethane Enamel finish being applied to railings.

PHOTOGRAPH #4



**BUILDING 27
SECTION C – UNIT #2727**

Both double windows passed re-testing by Independent Testing Agency that previously failed and were repaired by PGT.

PHOTOGRAPH #5



**BUILDING 27
SECTION C – UNIT #2727**

PGT has made repairs at metal to metal sill to jamb transitions with silicone sealants.

PHOTOGRAPH #6



**BUILDING 27
SECTION C – UNIT #2727**

PGT has made repairs at metal to metal sill to jamb transitions with silicone sealants.

PHOTOGRAPH #7



**BUILDING 27
SECTION C – UNIT #2727**

AAMA sticker required is missing from several windows.

PHOTOGRAPH #8



**BUILDING 27
SECTION A**

Overlap of both Super Jumbo Tex 60 and Tyvek HomeWrap WRB at outside corner are not 12 inches as specified.

PHOTOGRAPH #9



**BUILDING 27
SECTION B**

Debris and materials left remaining around building site not within a fenced construction area.

PHOTOGRAPH #10



**BUILDING 27
SECTION B**

Debris and materials left remaining around building site not within a fenced construction area.

PHOTOGRAPH #11



**BUILDING 27
SECTION B**

Debris and materials left remaining around building site not within a fenced construction area.

PHOTOGRAPH #12



**BUILDING 27
SECTION B**

Debris and materials left remaining around building site not within a fenced construction area.

PHOTOGRAPH #13



**BUILDING 27
SECTION A**

Debris and materials left remaining around building site not within a fenced construction area.

PHOTOGRAPH #14



**BUILDING 10
SECTION D**

Damages identified and marked for repairs.

PHOTOGRAPH #15



**BUILDING 10
SECTION D**

Damages identified and marked for repairs.

PHOTOGRAPH #16



**BUILDING 10
SECTION D**

Damages identified and marked for repairs.

PHOTOGRAPH #17



**BUILDING 10
SECTION D**

Damages identified and marked for repairs.

PHOTOGRAPH #18



**BUILDING 10
SECTION E**

Damages identified and marked for repairs.

PHOTOGRAPH #19



**BUILDING 10
SECTION E**

Damages identified and marked for repairs.

PHOTOGRAPH #20



**BUILDING 10
SECTION E**

Damages identified and marked for repairs.