

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 27 SECTION C

Contractor has installed screen enclosures.

PHOTOGRAPH #2



BUILDING 27 SECTION A

BASF representative has done sealant pull tests.

PHOTOGRAPH #3



**BUILDING 27
SECTION A – PUNCH ITEM**

Split seam at small section of soffit wood to soffit screen.

PHOTOGRAPH #4



**BUILDING 27
SECTION B- PUNCH ITEM**

Paint missed at balcony beam.

PHOTOGRAPH #5



**BUILDING 27
SECTION B – PUNCH ITEM**

White paint on bronze railing.

PHOTOGRAPH #6



**BUILDING 27
SECTION D- PUNCH ITEM**

Missed paint at upper corner of stucco.

PHOTOGRAPH #7



**BUILDING 27
SECTION F- PUNCH ITEM**

Cedar trim at balcony cracked.

PHOTOGRAPH #8



**BUILDING 27
SECTION B- PUNCH ITEM**

Excessive Stucco in control joint.

PHOTOGRAPH #9



**BUILDING 27
SECTION B- PUNCH ITEM**

Existing stucco cracked at bottom of breezeway wall.

PHOTOGRAPH #10



**BUILDING 27
SECTION B- PUNCH ITEM**

Existing stucco cracked at upper breezeway wall.

PHOTOGRAPH #11



**BUILDING 10
SECTION E**

Stucco sub-applied stucco accessories and metal lath.

PHOTOGRAPH #12



**BUILDING 10
SECTION F**

Stucco sub-contractor in process of applying JumboTex 60 and stucco accessories.

PHOTOGRAPH #13



**BUILDING 10
SECTION G**

Contractor has installed new PGT windows.

PHOTOGRAPH #14



**BUILDING 10
SECTION G**

Unit #1022- New PT deck boards at balcony.

PHOTOGRAPH #15



**BUILDING 10
SECTION H**

Contractor has protected A/C equipment from falling objects during demolition work.

PHOTOGRAPH #16



**BUILDING 10
SECTION H**

Framing damage identified and marked for repairs.

PHOTOGRAPH #17



**BUILDING 10
SECTION H**

Framing damage identified and marked for repairs.

PHOTOGRAPH #18



**BUILDING 10
SECTION H**

Framing damage identified and marked for repairs.

PHOTOGRAPH #19



**BUILDING 10
SECTION H**

Framing damage identified and marked for repairs.

PHOTOGRAPH #20



**BUILDING 10
SECTION H -UNIT #1022**

Contractor has performed framing scab and firewall repairs.

PHOTOGRAPH #21



**BUILDING 10
SECTION H -UNIT #1022**

Contractor has performed framing scab and firewall repairs.

PHOTOGRAPH #22



**BUILDING 10
SECTION H -UNIT #1021**

Contractor has performed framing scab and firewall repairs.

PHOTOGRAPH #23



**BUILDING 10
SECTION H -UNIT #1021**

Contractor has performed framing scab and firewall repairs.

PHOTOGRAPH #24



**BUILDING 10
SECTION F**

Contractor has installed Simpson Strong-Tie Connector straps at door header as per ESI#1.