

**PHOTOGRAPHS**

**PHOTOGRAPH #1**



**BUILDING 27  
SECTION B**

Contractor has completed punch list and cleaned site.

**PHOTOGRAPH #2**



**BUILDING 27  
SECTION F**

Contractor has completed punch list and cleaned site.

**PHOTOGRAPH #3**



**BUILDING 10  
SECTION D**

New sealant has been installed at window perimeter and stucco band has been primed.

**PHOTOGRAPH #4**



**BUILDING 10  
SECTION F**

Stucco sub-contractor has applied JumboTex 60, stucco accessories and lath.


**PHOTOGRAPH #5**



**BUILDING 10  
SECTION F**

Stucco sub-contractor has applied JumboTex 60 WRB, stucco accessories and lath.

**PHOTOGRAPH #6**



**BUILDING 10  
SECTION F**

Contractor has installed balcony deck kick out flashing.

**PHOTOGRAPH #7**



**BUILDING 10  
SECTION G**

Stucco sub-contractor installing  
JumboTex WRB over Tyvek HomeWrap.

**PHOTOGRAPH #8**



**BUILDING 10  
SECTION H**

Contractor performing framing repairs at  
subflooring, studs and headers.

**PHOTOGRAPH #9**



**BUILDING 10  
SECTION H**

Contractor installing Simpson Strong-Tie connectors and straps.

**PHOTOGRAPH #10**



**BUILDING 10  
SECTION H**

Termite contractor has applied Bora Care termite treatment at framing.

**PHOTOGRAPH #11**



**BUILDING 10  
SECTION H**

Contractor has performed gable end wall bracing and reinforcing.

**PHOTOGRAPH #12**



**BUILDING 10  
SECTION H- UNIT 1011**

Damaged drywall to be removed and repaired from inside unit.

**PHOTOGRAPH #13**



**BUILDING 10  
SECTION B**

Contractor in process of removal of stucco and sheathing.