

## PHOTOGRAPHS

**PHOTOGRAPH #1**



### **BUILDING 10 SECTION G**

Sub-Contractor applying JumboTex WRB,  
lath and stucco accessories.

**PHOTOGRAPH #2**



### **BUILDING 10 SECTION G**

Sub-Contractor applying JumboTex WRB,  
lath and stucco accessories.

**PHOTOGRAPH #3**



**BUILDING 10  
SECTION H**

Contractor performing application of plywood sheathing.

**PHOTOGRAPH #4**



**BUILDING 10  
SECTION H**

Pressure Treated plywood sheathing applied at lower section of wall.

**PHOTOGRAPH #5**



**BUILDING 10  
SECTION A**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #6**



**BUILDING 10  
SECTION A**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #7**



**BUILDING 10  
SECTION A**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #8**



**BUILDING 10  
SECTION B**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #9**



**BUILDING 10  
SECTION B**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #10**



**BUILDING 10  
SECTION B**

Framing damages assessed and marked for Contractor repairs. Additional demo required for further assessment.

**PHOTOGRAPH #11**



**BUILDING 10  
SECTION C**

Framing damages assessed and marked for Contractor repairs.

**PHOTOGRAPH #12**



**BUILDING 10  
SECTION D – UNIT #1018**

Contractor has installed new PGT window with DuPont flashings and begun drywall repairs.

**PHOTOGRAPH #13**



**BUILDING 10  
SECTION G – UNIT #1022**

Double window - Independent testing agency performed AAMA 502 water testing at new windows. No leaks were detected.

**PHOTOGRAPH #14**



**BUILDING 10  
SECTION G – UNIT #1022**

Double window - Independent testing agency performed AAMA 502 water testing at new windows. No leaks were detected.

**PHOTOGRAPH #15**



**BUILDING 10  
SECTION H – UNIT #1022**

Single window - Independent testing agency performed AAMA 502 water testing at new windows. No leaks were detected.

**PHOTOGRAPH #16**



**BUILDING 10  
SECTION H – UNIT #1022**

Single window - Independent testing agency performed AAMA 502 water testing at new windows. No leaks were detected.