

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 10 SECTION D

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #2



BUILDING 10 SECTION E

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #3



**BUILDING 10
SECTION F**

Stucco sub-contractor applying brown coat of stucco.

PHOTOGRAPH #4



**BUILDING 10
SECTION G**

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #5



**BUILDING 10
SECTION H**

Stucco sub-contractor applying stucco accessories and metal lath.

PHOTOGRAPH #6



**BUILDING 10
SECTION H**

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #7



**BUILDING 10
SECTION A**

Gap at sheathing corner.

PHOTOGRAPH #8



**BUILDING 10
SECTION A**

Contractor has sealed gap at sheathing corner.

PHOTOGRAPH #9



**BUILDING 10
SECTION B**

Simpson Strong-Tie Strapping installed at header repair.

PHOTOGRAPH #10



**BUILDING 10
SECTION C**

Simpson Strong-Tie HTT4 connector and Titen HD anchor required at framing to Bottom plate.

PHOTOGRAPH #11



**BUILDING 10
SECTION C**

Contractor has installed Simpson Strong-Tie HTT4 connector and Titen HD anchor at framing to Bottom plate.

PHOTOGRAPH #12



**BUILDING 10
SECTION C**

Bora Care termite treatment has been applied to framing by termite contractor.

PHOTOGRAPH #13



**BUILDING 10
SECTION C**

Contractor installing R-13 insulation where missing or damaged.