


PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 10
SECTION E**

Breezeway railings primed with
Encapsulon Epoxy Mastic Primer.

PHOTOGRAPH #2



**BUILDING 10
SECTION E**

Breezeway railings primed with
Encapsulon Epoxy Mastic Primer.


PHOTOGRAPH #3



**BUILDING 10
SECTION E**

Metal front doors prepped and protected for prime and finish paint.

PHOTOGRAPH #4



**BUILDING 10
SECTION E**

Screen enclosures being installed at lower units.

PHOTOGRAPH #5



**BUILDING 10
SECTION F**

Balcony railings finish painted and ready for installation.

PHOTOGRAPH #6



**BUILDING 10
SECTION F**

Roofing tiles removed at kick out flashing detail will be patched with full bed of roofing mastic before tiles are reinstalled.

PHOTOGRAPH #7



**BUILDING 10
SECTION G**

Breezeway railing exhibiting surface rust after paint removal. Contractor will remove surface rust prior to primer application.

PHOTOGRAPH #8



**BUILDING 10
SECTION H**

New stucco walls and trim being painted with Florida Paints Supercoat 100% acrylic.

PHOTOGRAPH #9



**BUILDING 10
SECTION B**

Sub-contractor has applied stucco accessories and metal lath in preparation for new stucco applications.

PHOTOGRAPH #10



**BUILDING 10
SECTION C**

New windows installed with DuPont flashings.