

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 10
SECTION D**

Delta performed and passed sealant
adhesion pull test at lower window.

PHOTOGRAPH #2



**BUILDING 10
SECTION D**

Delta performed and passed sealant
adhesion pull test at lower window.

PHOTOGRAPH #3



**BUILDING 10
SECTION E**

Breezeway railings finish painted with Florida Paints #7500WA Acrylic Aliphatic Gloss Enamel.

PHOTOGRAPH #4



**BUILDING 10
SECTION E**

Metal front doors finish painted with Florida Paints AllGrip exterior acrylic paint.

PHOTOGRAPH #5



**BUILDING 10
SECTION F**

Balcony railings and enclosures installed.

PHOTOGRAPH #6



**BUILDING 10
SECTION G**

Unit #1021- Interior finish work at new windows in progress.

PHOTOGRAPH #7



**BUILDING 10
SECTION A**

Stucco scratch and brown coat applications in progress.

PHOTOGRAPH #8



**BUILDING 10
SECTION B**

Stucco brown coat applied over new metal lath and stucco accessories.

PHOTOGRAPH #9



**BUILDING 10
SECTION C**

Sub-contractor applying stucco accessories and metal lath in preparation for new stucco applications.

PHOTOGRAPH #10



**BUILDING 10
SECTION D**

Sub-contractor applying stucco scratch coat over new accessories and metal lath.