

PHOTOGRAPHS


PHOTOGRAPH #1



BUILDING 10 SECTION G

Stucco sub-contractor has completed finish coat & painted stucco.

PHOTOGRAPH #2



BUILDING 10 SECTION F

Void in stucco at sidewall.

PHOTOGRAPH #3



**BUILDING 10
SECTION H**

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #4



**BUILDING 10
SECTION C**

Stucco sub-contractor has completed installation of stucco accessories and metal lath.


PHOTOGRAPH #5



**BUILDING 10
SECTION B**

Stucco sub-contractor applying stucco accessories and metal lath.

PHOTOGRAPH #6



**BUILDING 10
SECTION A**

Contractor has completed installation of PGT windows. Contractor to install fastener a minimum 1/4" from edge of flange.