

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 5
SECTION D**

Contractor has made wood framing repairs as marked at studs, headers, sub flooring, top and bottom plates.

PHOTOGRAPH #2



**BUILDING 5
SECTION D**

Contractor has made wood framing repairs as marked at studs, headers, sub flooring, top and bottom plates.

PHOTOGRAPH #3



**BUILDING 5
SECTION D
ATTIC- UNIT #527**

Repairs performed and quantified at gussets and truss framing.

PHOTOGRAPH #4



**BUILDING 5
SECTION D
ATTIC- UNIT #527**

Repairs performed and quantified at firewalls.

PHOTOGRAPH #5



**BUILDING 5
SECTION D
ATTIC- UNIT #525**

Damaged trusses have been repaired and quantified.

PHOTOGRAPH #6



**BUILDING 5
SECTION D
ATTIC- UNIT #525**

Damaged trusses have been repaired and quantified.

PHOTOGRAPH #7



**BUILDING 5
SECTION E**

Framing damage marked for repairs at Breezeway.

PHOTOGRAPH #8



**BUILDING 5
SECTION F**

Existing damaged balcony deck boards covered with owner's tile decking system.

PHOTOGRAPH #9



**BUILDING 5
SECTION F**

Framing damage below balconies.

PHOTOGRAPH #10



**BUILDING 5
SECTION F**

Balcony railings removed for repairs and preparation for painting.

PHOTOGRAPH #11



**BUILDING 5
SECTION F**

Existing damage and poor condition of balcony deck boards to me removed and replaced.