

PHOTOGRAPHS


PHOTOGRAPH #1



**BUILDING 10
SECTION F**

Balcony railing brackets welded, fastened and sealed.

PHOTOGRAPH #2



**BUILDING 10
SECTION F**

Anchor bolts and railing brackets receiving new paint touch ups.

PHOTOGRAPH #3



**BUILDING 10
SECTION B**

Damaged wood trim at wood doors on balconies removed and replaced.

PHOTOGRAPH #4



**BUILDING 10
SECTION B**

Debris stuck in sealants removed or sealant replaced at windows.

PHOTOGRAPH #5



**BUILDING 10
SECTION G**

Unit #1022- Fire wall repairs not performed as per ESI # 2 and has cracked.

PHOTOGRAPH #6



**BUILDING 10
SECTION G**

Unit #1022- Fire wall repairs removed and replaced as per ESI # 2.

PHOTOGRAPH #7



**BUILDING 10
SECTION B**

Railing brackets installed and painted.