

## PHOTOGRAPHS

**PHOTOGRAPH #1**



**BUILDING 5  
SECTION D**

Contractor has applied new 15/32" sheathing.

**PHOTOGRAPH #2**



**BUILDING 5  
SECTION D**

Contractor has applied new 15/32" sheathing.

**PHOTOGRAPH #3**



**BUILDING 5  
SECTION D**

Contractor has applied Dupont Tyvek HomeWrap.

**PHOTOGRAPH #4**



**BUILDING 5  
SECTION E**

Simpson Strong -Tie strapping placed at new window opening repairs. Bora-Care termite treatment applied at framing.

**PHOTOGRAPH #5**



**BUILDING 5  
SECTION E**

New pressure treated plywood sheathing sealed at base plate.

**PHOTOGRAPH #6**



**BUILDING 5  
SECTION E**

Wood framing repairs performed at breezeway.


**PHOTOGRAPH #7**



**BUILDING 5  
SECTION F**

Wood framing repairs performed at window header and window framing.

**PHOTOGRAPH #8**



**BUILDING 5  
SECTION F**

**Unit #526-** Contractor working on framing and decking repairs at balcony.

**PHOTOGRAPH #9**



**BUILDING 5  
SECTION F**

**Unit #526-** Wood framing damage at balcony inspected and marked for repairs.

**PHOTOGRAPH #10**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #525-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #11**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #525-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #12**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #526-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #13**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #526-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #14**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #524-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #15**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #524-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #16**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #523-** Framing repairs and fire wall repairs reviewed and verified.

**PHOTOGRAPH #17**



**BUILDING 5  
ATTIC REPAIRS**

**Unit #523-** Framing repairs and fire wall repairs reviewed and verified.