

## PHOTOGRAPHS

PHOTOGRAPH #1



### **BUILDING 5 SECTION F**

Transition from existing roof trim and soffit at head of new stucco stop is open and requires sealant.

PHOTOGRAPH #2



### **BUILDING 5 SECTION F**

Contractor has sealed transition from existing roof trim and soffit at head of new stucco stop as directed by Delta.


**PHOTOGRAPH #3**



**BUILDING 5  
SECTION F**

New stucco walls have been finished painted and new cedar trim applied to balcony facing.

**PHOTOGRAPH #4**



**BUILDING 5  
SECTION G**

Contractor is applying Florida Paints Urethane Gloss Enamel finish paint over primer at stairways.

**PHOTOGRAPH #5**



**BUILDING 5  
SECTION G**

Contractor has applied Florida paints AllGrip Exterior Acrylic on entrance doors.

**PHOTOGRAPH #6**



**BUILDING 5  
SECTION G**

Stucco remaining at balcony wall has delaminated and will require patching with new stucco and painting.

**PHOTOGRAPH #7**



**BUILDING 5  
SECTION H**

Contractor in process of applying paint prime coat to new stucco.

**PHOTOGRAPH #8**



**BUILDING 5  
SECTION A**

Final finish coat of stucco applied at walls and cedar trim installed at balcony facing.


**PHOTOGRAPH #9**



**BUILDING 5  
SECTION B**

Contractor installing new BASF sealants at window perimeters.

**PHOTOGRAPH #10**



**BUILDING 5  
SECTION C**

Breezeway railings have been finish coated with Florida Paints Acrylic Gloss Aliphatic Enamel.

**PHOTOGRAPH #11**



**BUILDING 5  
SECTION C**

Breezeway railings have been finish coated with Florida Paints Acrylic Gloss Aliphatic Enamel.

**PHOTOGRAPH #12**



**BUILDING 5  
SECTION C**

Stucco Sub-contractor has completed three coat system of stucco.

**PHOTOGRAPH #13**



**BUILDING 5  
SECTION C**

Gap in soffit has been filled and finish painted.

**PHOTOGRAPH #14**



**BUILDING 23  
SECTION H**

PGT windows being installed at 2<sup>nd</sup> floor with manufacturer supplied window operation control devises for compliance with Florida Building codes.

**PHOTOGRAPH #15**



**BUILDING 23  
SECTION H**

PGT windows being installed at 2<sup>nd</sup> floor with manufacturer supplied window operation control devises for compliance with Florida Building codes.

**PHOTOGRAPH #16**



**BUILDING 23  
SECTION H**

GreenHeck attic louvers installed with DuPont flashings as per manufacturer's instructions.

**PHOTOGRAPH #17**



**BUILDING 23  
SECTION G**

Tyvek HomeWrap, Dupont flashings and PGT windows installed.

**PHOTOGRAPH #18**



**BUILDING 23  
SECTION F**

Contractor has attached new plywood sheathing to framing as per project manual and drawings.

**PHOTOGRAPH #19**



**BUILDING 23  
SECTION F**

Contractor installing missing Simpson Strong-Tie connectors identified by Delta.

**PHOTOGRAPH #20**



**BUILDING 23  
SECTION F**

Framing repairs, strapping, connectors, and termite treatment in place for inspection.

**PHOTOGRAPH #21**



**BUILDING 23  
SECTION E -BREEZEWAY**

Previous roof sheathing damage observed before new soffit is installed. Roof repairs not part of current scope and to be repaired by owners.

**PHOTOGRAPH #22**



**BUILDING 23  
SECTION E**

Framing repairs, strapping, connectors, and termite treatment in place for inspection.

**PHOTOGRAPH #23**



**BUILDING 23  
SECTION E**

Framing repairs, strapping, connectors, and termite treatment in place for inspection.