


PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 5
SECTION B**

Contractor Installing new screen enclosures where removed for repairs.

PHOTOGRAPH #2



**BUILDING 5
SECTION B**

Stainless steel fasteners used for screen enclosures.

PHOTOGRAPH #3



**BUILDING 5
SECTION B**

Stainless steel fasteners used for screen enclosures.


PHOTOGRAPH #4



**BUILDING 5
SECTION E**

Balcony railing attachments flanges have been welded to railings and being attached with lag screws.

PHOTOGRAPH #5



**BUILDING 5
SECTION E**

Breezeway railing pickets marked for welding repairs.

PHOTOGRAPH #6



**BUILDING 5
SECTION D
EXTERIOR PUNCH LIST**

Sealant missing at transition to be sealed and touched up.

PHOTOGRAPH #7



**BUILDING 5
SECTION D
EXTERIOR PUNCH LIST**

Drips at white window bands to be removed and repainted.

PHOTOGRAPH #8



**BUILDING 5
SECTION E
EXTERIOR PUNCH LIST**

Soiled sealant at bottom of windows to be painted white.

PHOTOGRAPH #9



**BUILDING 5
SECTION E
EXTERIOR PUNCH LIST**

Breezeway railing picket to be repaired and repainted.

PHOTOGRAPH #10



**BUILDING 5
SECTION E
EXTERIOR PUNCH LIST**

Paint missing below emergency lights to be touched up.

PHOTOGRAPH #11



**BUILDING 5
SECTION F
EXTERIOR PUNCH LIST**

Paint on dryer vent has alligatored and will require repainting.

PHOTOGRAPH #12



**BUILDING 5
SECTION G
EXTERIOR PUNCH LIST**

Stucco covering stucco joint to be removed and touched up.

PHOTOGRAPH #13



**BUILDING 5
SECTION G
EXTERIOR PUNCH LIST**

Bronze paint drip on unit numbers to be touched up.

PHOTOGRAPH #14



**BUILDING 5
SECTION G
EXTERIOR PUNCH LIST**

Paint missing below emergency lights to be touched up.

PHOTOGRAPH #15



**BUILDING 5
SECTION G
EXTERIOR PUNCH LIST**

Paint missing in corner to be touched up.

PHOTOGRAPH #16



**BUILDING 5
SECTION H
EXTERIOR PUNCH LIST**

Paint drip to be touched up.

PHOTOGRAPH #17



**BUILDING 5
SECTION B
EXTERIOR PUNCH LIST**

Stucco on window frame to be removed.

PHOTOGRAPH #18



**BUILDING 5
SECTION B
EXTERIOR PUNCH LIST**

Missing paint at dryer vent to be touched up.

PHOTOGRAPH #19



**BUILDING 5
SECTION C
EXTERIOR PUNCH LIST**

Paint and sealant on window glass to be cleaned.

PHOTOGRAPH #20



**BUILDING 23
SECTION E**

New PGT windows installed with Tyvek/Dupont flashing.

PHOTOGRAPH #21



**BUILDING 23
SECTION D**

Additional damage identified and marked for repairs.

PHOTOGRAPH #22



**BUILDING 23
SECTION D**

Additional damage identified and marked for repairs.

PHOTOGRAPH #23



**BUILDING 23
SECTION D**

Subfloor repairs at gable end repairs have been performed.

PHOTOGRAPH #24



**BUILDING 23
SECTION D**

BoraCare Termite treatment has been applied at all framing.

PHOTOGRAPH #25



**BUILDING 23
SECTION D**

Simpson Strong-Tie straps, connectors and clips have been installed and inspected.

PHOTOGRAPH #26



**BUILDING 23
SECTION D
ATTIC UNIT # 2327**

Repairs made at framing trusses and firewalls.

PHOTOGRAPH #27



**BUILDING 23
SECTION D
ATTIC UNIT # 2327**

Repairs made at framing trusses and firewalls.

PHOTOGRAPH #28



**BUILDING 23
SECTION D
ATTIC UNIT # 2328**

Repairs made at framing trusses and firewalls.

PHOTOGRAPH #29



**BUILDING 23
SECTION D
ATTIC UNIT # 2328**

Repairs made at framing trusses and firewalls.

PHOTOGRAPH #30



**BUILDING 23
SECTION C**

Framing damage identified and marked by Delta for repairs.

PHOTOGRAPH #31



**BUILDING 23
SECTION C**

Framing damage identified and marked by Delta for repairs.

PHOTOGRAPH #32



**BUILDING 23
SECTION C**

Breezeway column support pedestal marked for repair.

PHOTOGRAPH #33



**BUILDING 23
SECTION B**

Framing and balcony deck damage identified and marked by Delta for repairs.

PHOTOGRAPH #34



**BUILDING 23
SECTION B**

Framing and balcony deck damage identified and marked by Delta for repairs.

PHOTOGRAPH #35



**BUILDING 23
SECTION B**

Framing and balcony deck damage identified and marked by Delta for repairs.

PHOTOGRAPH #36



**BUILDING 23
SECTION A**

Framing damage identified and marked by Delta for repairs.