

## PHOTOGRAPHS


**PHOTOGRAPH #1**



### **BUILDING 5 SECTION B**

New screen enclosures installed, and balcony railing attachments completed.

**PHOTOGRAPH #2**



### **BUILDING 5 SECTION B EXTERIOR PUNCH LIST**

Breezeway railings pickets to be repaired and touched up.

**PHOTOGRAPH #3**



**BUILDING 5  
SECTION D  
EXTERIOR PUNCH LIST**

Sealant has been installed at transition and touched up.

**PHOTOGRAPH #4**



**BUILDING 5  
SECTION D  
EXTERIOR PUNCH LIST**

Drips at white window bands removed and repainted.

**PHOTOGRAPH #5**



**BUILDING 5  
SECTION E  
EXTERIOR PUNCH LIST**

Soiled sealant at bottom of windows painted white.

**PHOTOGRAPH #6**



**BUILDING 5  
SECTION E  
EXTERIOR PUNCH LIST**

Paint missing below emergency lights touched up.

**PHOTOGRAPH #7**



**BUILDING 5  
SECTION F  
EXTERIOR PUNCH LIST**

Dryer vent has been repainted.

**PHOTOGRAPH #8**



**BUILDING 5  
SECTION G  
EXTERIOR PUNCH LIST**

Stucco covering stucco joint has been removed and touched up.

**PHOTOGRAPH #9**



**BUILDING 5  
SECTION G  
EXTERIOR PUNCH LIST**

Bronze paint drip on unit numbers have been touched up.

**PHOTOGRAPH #10**



**BUILDING 5  
SECTION G  
EXTERIOR PUNCH LIST**

Paint missing below emergency lights touched up.


**PHOTOGRAPH #11**



**BUILDING 5  
SECTION G  
EXTERIOR PUNCH LIST**

Paint missing in corner has been touched up.

**PHOTOGRAPH #12**



**BUILDING 5  
SECTION H  
EXTERIOR PUNCH LIST**

Paint drip has been touched up.

**PHOTOGRAPH #13**



**BUILDING 5  
SECTION B  
EXTERIOR PUNCH LIST**

Stucco on window frame removed.

**PHOTOGRAPH #14**



**BUILDING 5  
SECTION C  
EXTERIOR PUNCH LIST**

Paint and sealant on window glass cleaned.

**PHOTOGRAPH #15**



**BUILDING 23  
SECTION H  
Unit #2322 – Water testing**

Independent Testing Agency performed AAMA 502 water testing at single window with no leaks.

**PHOTOGRAPH #16**



**BUILDING 23  
SECTION G  
Unit #2322 – Water testing**

Independent Testing Agency performed AAMA 502 water testing at double window with no leaks.

**PHOTOGRAPH #17**



**BUILDING 23  
SECTION E**

New soffit and soffit screen has been installed.

**PHOTOGRAPH #18**



**BUILDING 23  
SECTION D**

Contractor applying new plywood sheathing at gable end.

**PHOTOGRAPH #19**



**BUILDING 23  
SECTION D**

Delta marked missing fasteners at new sheathing.

**PHOTOGRAPH #20**



**BUILDING 23  
SECTION D**

Contractor has corrected missing fasteners at plywood sheathing.

**PHOTOGRAPH #21**



**BUILDING 23  
SECTION C**

Repairs made at framing studs, plates and subflooring.

**PHOTOGRAPH #22**



**BUILDING 23  
SECTION C**

Contractor installing Titan anchors at base plate.

**PHOTOGRAPH #23**



**BUILDING 23  
SECTION C**

Breezeway railings being prepared for priming and painting.

**PHOTOGRAPH #24**



**BUILDING 23  
SECTION B**

Repairs in progress at damaged balcony framing and decks.

**PHOTOGRAPH #25**



**BUILDING 23  
SECTION B**

Live termites active at damaged balcony edge rim joist.

**PHOTOGRAPH #26**



**BUILDING 23  
SECTION B**

Live termites active at damaged balcony edge rim joist.

**PHOTOGRAPH #27**



**BUILDING 23  
SECTION B**

Additional damage discovered and marked for repairs by Delta.

**PHOTOGRAPH #28**



**BUILDING 23  
SECTION B**

Additional damage discovered and marked for repairs by Delta.

**PHOTOGRAPH #29**



**BUILDING 23  
SECTION B**

Framing and balcony deck repairs in progress.

**PHOTOGRAPH #30**



**BUILDING 23  
SECTION B**

R-19 insulation on site for replacement of damaged or missing insulation.

**PHOTOGRAPH #31**



**BUILDING 23  
SECTION A**

Breezeway railing damage will require welding repairs.