

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 23 SECTION H

Sub-contractor has made corrections marked by Delta where sealant is required.

PHOTOGRAPH #2



BUILDING 23 SECTION G

Sub-contractor has made corrections marked by Delta where sealant is required.

PHOTOGRAPH #3



**BUILDING 23
SECTION G**

Sub-contractor has made corrections at new stucco accessories to kick out balcony flashing as marked by Delta.


PHOTOGRAPH #4



**BUILDING 23
SECTION F**

Sub-contractor has applied plastic protection at windows and balcony surfaces in preparation for stucco application.

PHOTOGRAPH #5



**BUILDING 23
SECTION D**

New stucco stop weep screed has been flashed with Dupont straight flash to the new plywood sheathing.

PHOTOGRAPH #6



**BUILDING 23
SECTION C**

Tyvek HomeWrap, Dupont flashings and new PGT windows have been installed.

PHOTOGRAPH #7



**BUILDING 23
SECTION B**

Tyvek HomeWrap, Dupont flashings and new PGT windows have been installed.

PHOTOGRAPH #8



**BUILDING 23
SECTION A**

New PGT window fin fastening confirmed at proper distance per manufacturers NOAs.

PHOTOGRAPH #9



**BUILDING 23
SECTION A**

Stucco contractor has set up for mixing stucco.

PHOTOGRAPH #10



**BUILDING 23
SECTION A**

BROCO Stucco bag mix approved for application.

PHOTOGRAPH #11



**BUILDING 23
STORAGE AREA**

Contractor spray priming balcony railings with Florida Paints Encapsulant epoxy mastic primer.

PHOTOGRAPH #12



**BUILDING 23
STORAGE AREA**

Contractor spray priming balcony railings with Florida Paints Encapsulant epoxy mastic primer.

PHOTOGRAPH #13



**BUILDING 21
SECTION H**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #14



**BUILDING 21
SECTION H**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #15



**BUILDING 21
SECTION H**

Contractor performing damage repairs marked at framing and gable end reinforcement repairs.

PHOTOGRAPH #16



**BUILDING 21
SECTION G**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #17



**BUILDING 21
SECTION G**

Contractor performing damaged framing repairs.

PHOTOGRAPH #18



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged framing for repairs

PHOTOGRAPH #19



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged window headers for repairs.

PHOTOGRAPH #20



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged deck framing and decking for repairs and replacement.

PHOTOGRAPH #21



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged deck framing and decking for repairs and replacement.

PHOTOGRAPH #22



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #23



**BUILDING 21
SECTION F**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #24



**BUILDING 21
SECTION E**

Delta has inspected and marked damaged framing for repairs.

PHOTOGRAPH #25



**BUILDING 21
SECTION E**

Delta has inspected and marked damaged framing for repairs.