

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 21 SECTION F

Steel angles welded onto railing for fastening to walls at balconies.

PHOTOGRAPH #2



BUILDING 21 UNIT #2124- SECTION F

Interior drywall and windowsill repaired, textured, and primed.

PHOTOGRAPH #3



**BUILDING 21
SECTION B**

Removal and repairs of messy transition sealants in progress.

PHOTOGRAPH #4



**BUILDING 21
SECTION B**

Removal and repairs of messy transition sealants in progress.


PHOTOGRAPH #5



**BUILDING 21
SECTION B- UNIT #2121**

Interior drywall and windowsill repaired, textured, and primed.

PHOTOGRAPH #6



**BUILDING 21
SECTION B- UNIT #2121**

PGT factory installed WOCD hardware at 2nd floor windows.


PHOTOGRAPH #7



**BUILDING 21
SECTION B- UNIT #2132**

Windows inspected from interior for proper gaps, Dupont flashing details and sealant details to meet specifications and manufacturer's NOA requirements.

PHOTOGRAPH #8



**BUILDING 21
SECTION B- UNIT #2132**

Windows inspected from interior for proper gaps, Dupont flashing details and sealant details to meet specifications and manufacturer's NOA requirements.

PHOTOGRAPH #9



**BUILDING 21
SECTION B**

Paint on several new dryer vents failing and will required correction.

PHOTOGRAPH #10



**BUILDING 20
SECTION D**

Contractor is providing heavy plastic protection at walls where stucco has been removed during repairs.

PHOTOGRAPH #11



**BUILDING 20
SECTION D**

Repairs performed at wall framing,
window framing and subflooring.

PHOTOGRAPH #12



**BUILDING 20
SECTION D**

Repairs performed at wall framing,
window framing and subflooring.

PHOTOGRAPH #13



**BUILDING 20
SECTION E**

Removal of existing stucco and Thermoply sheathing exposed damaged framing that partially collapsed when stucco was removed. Immediate shoring is required until repairs are in place.

PHOTOGRAPH #14



**BUILDING 20
SECTION E**

Removal of existing stucco and Thermoply sheathing exposed damaged framing that partially collapsed when stucco was removed. Immediate shoring is required until repairs are in place.

PHOTOGRAPH #15



**BUILDING 20
SECTION E**

Removal of existing stucco and Thermoply sheathing exposed damaged framing that partially collapsed when stucco was removed. Immediate shoring is required until repairs are in place.

PHOTOGRAPH #16



**BUILDING 20
SECTION E**

Roof sheathing damage and evidence of active roof leaks.

PHOTOGRAPH #17



**BUILDING 20
SECTION F**

Roof sheathing damage and evidence of active roof leaks.

PHOTOGRAPH #18



**BUILDING 23
UNIT # 2325**

Firewall where removed for additional investigation has been replaced.

PHOTOGRAPH #19



**BUILDING 23
UNIT # 2316**

Protective coverings removed from windows. Identified during interior walk though.

PHOTOGRAPH #20



**BUILDING 23
UNIT # 2322**

Broken WOCD replaced at new PGT window. Identified during interior walk though.

PHOTOGRAPH #21



**BUILDING 23
UNIT # 2322**

Broken WOCD replaced at new PGT window. Identified during interior walk though.