

**PHOTOGRAPHS**

**PHOTOGRAPH #1**



**BUILDING 20  
SECTION D**

Installation of Tyvek weather barrier defects corrected by contractor.

**PHOTOGRAPH #2**



**BUILDING 20  
SECTION D**

Tyvek seam not taped has been corrected by contractor above vent.


**PHOTOGRAPH #3**



**BUILDING 20  
SECTION D- UNIT #2027**

Independent testing agency performed and passed AAMA 502 water testing at 2<sup>nd</sup> floor single window.

**PHOTOGRAPH #4**



**BUILDING 20  
SECTION D- UNIT #2027**

Independent testing agency performed and passed AAMA 502 water testing at 2<sup>nd</sup> floor single window.

**PHOTOGRAPH #5**



**BUILDING 20  
SECTION D- UNIT #2027**

Independent testing agency performed and passed AAMA 502 water testing at 2<sup>nd</sup> floor double windows.

**PHOTOGRAPH #6**



**BUILDING 20  
SECTION D- UNIT #2027**

Independent testing agency performed and passed AAMA 502 water testing at 2<sup>nd</sup> floor double windows.

**PHOTOGRAPH #7**



**BUILDING 20  
SECTION D- ATTIC 2027**

Truss scabs, gussets and fire wall repairs performed.

**PHOTOGRAPH #8**



**BUILDING 20  
SECTION D- ATTIC 2027**

Truss scabs, gussets and fire wall repairs performed.


**PHOTOGRAPH #9**



**BUILDING 20  
SECTION D- ATTIC 2028**

Truss scabs, gussets and fire wall repairs performed.

**PHOTOGRAPH #10**



**BUILDING 20  
SECTION D- ATTIC 2028**

Truss scabs, gussets and fire wall repairs performed.

**PHOTOGRAPH #11**



**BUILDING 20  
SECTION D**

Simpson Strong -Tie HGA 10 clips have not been installed at top plate to new reinforcing studs as per specifications and drawings.

**PHOTOGRAPH #12**



**BUILDING 20  
SECTION E**

Full framing repairs performed at breezeway.

**PHOTOGRAPH #13**



**BUILDING 20  
SECTION E**

Finish painting in progress at Balconies and patios, with Florida Paints.

**PHOTOGRAPH #14**



**BUILDING 20  
SECTION F**

Additional repairs performed at patio door headers and walls.

**PHOTOGRAPH #15**



**BUILDING 20  
SECTION F**

Additional repairs performed at patio door headers and walls.

**PHOTOGRAPH #16**



**BUILDING 20  
SECTION G**

Framing repairs at breezeway and walls in progress.

**PHOTOGRAPH #17**



**BUILDING 20  
SECTION G**

Additional termite damage to be repaired,  
extending into breezeway walls.

**PHOTOGRAPH #18**



**BUILDING 20  
SECTION G**

Framing repairs at balconies and walls in  
progress.

**PHOTOGRAPH #19**



**BUILDING 20  
SECTION H**

JumboTex WRB and stucco accessories applications have begun.