

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 20 SECTION H

Sealant adhesion pull test performed at window perimeter confirming sealant application and performance.

PHOTOGRAPH #2



BUILDING 20 SECTION H

Sealant adhesion pull test performed at window perimeter confirming sealant application and performance

PHOTOGRAPH #3



**BUILDING 20
SECTION A**

Stairway railings primed with Florida Paints Encapsulon industrial epoxy mastic primer.

PHOTOGRAPH #4



**BUILDING 20
SECTION B**

New stucco primed and painted with Florida paints acrylic coatings.

PHOTOGRAPH #5



**BUILDING 20
SECTION C**

Three coat 7/8" stucco system applied.
Wet curing in progress.

PHOTOGRAPH #6



**BUILDING 20
SECTION D**

Three coat 7/8" stucco system applied.
Wet curing in progress.

PHOTOGRAPH #7



**BUILDING 20
SECTION E**

Stucco accessories and metal lathing applications in progress.

PHOTOGRAPH #8



**BUILDING 20
SECTION F**

Stucco accessories and metal lathing applications in progress.

PHOTOGRAPH #9



**BUILDING 20
UNIT # 2016- SECTION F**

Contractor applying finish drywall and new windowsills at new window areas.

PHOTOGRAPH #10



**BUILDING 20
SECTION F**

Kickout flashings at balconies repositioned for stucco application consistency.

PHOTOGRAPH #11



**BUILDING 20
SECTION F**

Stairway railings primed with Florida Paints Encapsulon industrial epoxy mastic primer.

PHOTOGRAPH #12



**BUILDING 20
SECTION F**

Railings removed from balconies prepped and primed with Encapsulon industrial epoxy mastic primer.

PHOTOGRAPH #13



**BUILDING 20
SECTION G**

JumboTex water resistant barrier application in progress.