

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 20
SECTION A**

Finish painting completed at new stucco
and balcony trim wood.

PHOTOGRAPH #2



**BUILDING 20
SECTION B**

Finish painting completed at new stucco
and balcony trim wood.

PHOTOGRAPH #3



**BUILDING 20
SECTION B**

Roofing Kick out flashing details performed and roof tiles re set.

PHOTOGRAPH #4



**BUILDING 20
SECTION B**

New roofing mastic applied at kick out flashing details before roof tiles replaced.

PHOTOGRAPH #5



**BUILDING 20
SECTION C**

Finish painting completed at new stucco and balcony trim wood.

PHOTOGRAPH #6



**BUILDING 20
SECTION D - UNIT #2018**

Contractor has installed additional fastener at window head as corrective measure in compliance with PGT engineering letter.


PHOTOGRAPH #7



**BUILDING 20
SECTION E**

Stucco accessories and metal lathing applications inspected and approved for stucco applications.

PHOTOGRAPH #8



**BUILDING 20
SECTION F- UNIT #2026**

Contractor applying finish drywall and new windowsills at new window areas.

PHOTOGRAPH #9



**BUILDING 20
SECTION F- UNIT #2026**

New interior perimeter sealants in compliance with AAMA window installation guidelines.

PHOTOGRAPH #10



**BUILDING 20
SECTION G**

Stucco accessories and metal lathing applications in progress.