

PHOTOGRAPHS


PHOTOGRAPH #1



BUILDING 20 SECTION B

Newly painted railings re installed at balconies with lag bolts as per drawings.


PHOTOGRAPH #2



BUILDING 20 SECTION C

Florida Paints, Hi-performance aliphatic Urethane Enamel spray applied at stairway railings.

PHOTOGRAPH #3



**BUILDING 20
SECTION C**

Florida Paints, Hi-performance aliphatic Urethane Enamel spray applied at stairway railings.

PHOTOGRAPH #4



**BUILDING 20
SECTION C**

Newly painted railings re installed at balconies with lag bolts as per drawings.

PHOTOGRAPH #5



**BUILDING 20
SECTION C**

Newly painted railings re installed at balconies with lag bolts as per drawings.

PHOTOGRAPH #6



**BUILDING 20
SECTION F**

Stucco accessories and metal lathing applications inspected and approved for stucco applications.

PHOTOGRAPH #7



**BUILDING 20
SECTION F**

Stucco and soffit areas above roof tiles have not been finish painted.

PHOTOGRAPH #8



**BUILDING 20
SECTION G**

Stucco accessories and metal lathing applications inspected and approved for stucco applications.