

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 1 SECTION H

Existing stucco and Thermo-ply removed.

PHOTOGRAPH #2



BUILDING 1 SECTION H

Damaged framing marked for repairs at wall studs, plates, and window framing.

PHOTOGRAPH #3



**BUILDING 1
SECTION H**

Damaged framing marked for repairs at wall studs, plates, and window framing.

PHOTOGRAPH #4



**BUILDING 1
SECTION H**

Damaged framing marked for repairs at wall studs, plates, and window framing.

PHOTOGRAPH #5



**BUILDING 1
SECTION H**

Open wall protected with heavy plastic sheathing.

PHOTOGRAPH #6



**BUILDING 1
SECTION G**

Removal of stucco and Thermo-ply in progress.

PHOTOGRAPH #7



**BUILDING 1
SECTION G**

Roof sheathing damage exposed. Active leaks observed at several locations.

PHOTOGRAPH #8



**BUILDING 1
SECTION G**

Roof sheathing damage exposed. Active leaks observed at several locations.

PHOTOGRAPH #9



**BUILDING 1
SECTION G**

Balcony railings removed for re-painting prior to reinstallation.

PHOTOGRAPH #10



**BUILDING 1
SECTION F**

Construction fencing provided at site perimeters for pedestrian safety.

PHOTOGRAPH #11



**BUILDING 1
SECTION F**

Removal of stucco and Thermo-ply in progress.