

## PHOTOGRAPHS

PHOTOGRAPH #1



### BUILDING 20 SECTION A

Reinstalled rails require welded angle re attached and fastened to wall.

PHOTOGRAPH #2



### BUILDING 20 SECTION A

Stucco contractor's removal of equipment and cleanup work required.

**PHOTOGRAPH #3**



**BUILDING 20  
SECTION A**

Breezeway floors finish painted.

**PHOTOGRAPH #4**



**BUILDING 20  
SECTION C**

Breezeway floors finish painted.

**PHOTOGRAPH #5**



**BUILDING 20  
SECTION D**

Clean up of debris and construction fencing required.

**PHOTOGRAPH #6**



**BUILDING 20  
SECTION F**

Cedar trim over built-up beam repair not covering properly at bottom edge.

**PHOTOGRAPH #7**



**BUILDING 20  
SECTION F**

HVAC electrical boxes not re attached and sealed to stucco.

**PHOTOGRAPH #8**



**BUILDING 20  
SECTION G**

Stucco repairs do not blend into existing stucco at breezeway walls as required.