

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 20 SECTION A

Balcony rails re-attached to framing at top rails.

PHOTOGRAPH #2



BUILDING 20 SECTION C

Stucco patched above cedar beam in breezeway.

PHOTOGRAPH #3



**BUILDING 20
SECTION H**

Stucco contractor has removed materials and equipment from parking area. Parking stops removed by others.