

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 1 SECTION F

Type C1A balcony repairs have begun on built up beams and columns.

PHOTOGRAPH #2



BUILDING 1 SECTION F

Balcony column concrete curbs have been poured in place.

PHOTOGRAPH #3



**BUILDING 1
SECTION F**

Balcony column concrete curbs have been poured in place.

PHOTOGRAPH #4



**BUILDING 1
SECTION F**

Wood framing repairs have begun at wall studs, window openings and headers.

PHOTOGRAPH #5



**BUILDING 1
SECTION G**

Stairway railing preparation in progress. Removing all rust and previous coatings by hand grinding.

PHOTOGRAPH #6



**BUILDING 1
SECTION G**

Stairway railing preparation in progress. Removing all rust and previous coatings by hand grinding.

PHOTOGRAPH #7



**BUILDING 1
STORAGE AREA**

New yellow pine lumber and plywood sheathing delivered for repairs.