

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 1 SECTION H

Stucco sub-contractor mixing stucco at staging area.

PHOTOGRAPH #2



BUILDING 1 SECTION H

Stucco sub-contractor has applied scratch coat and begun brown coat.

PHOTOGRAPH #3



**BUILDING 1
SECTION H**

Stucco sub-contractor has completed finish coat of stucco.

PHOTOGRAPH #4



**BUILDING 1
SECTION G**

Stucco sub-contractor has applied scratch coat and begun brown coat.

PHOTOGRAPH #5



**BUILDING 1
SECTION F**

Stucco contractor has protected windows and other adjacent surfaces from stucco applications.

PHOTOGRAPH #6



**BUILDING 1
UNIT #123 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #7



**BUILDING 1
UNIT #123 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #8



**BUILDING 1
UNIT #126 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #9



**BUILDING 1
UNIT #126 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #10



**BUILDING 1
UNIT #127 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #11



**BUILDING 1
UNIT #127 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #12



**BUILDING 1
UNIT #128 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #13



**BUILDING 1
UNIT #128 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #14



**BUILDING 1
UNIT #128 – ATTIC**

3M fire barrier sealant applied at fire wall penetrations.

PHOTOGRAPH #15



**BUILDING 2
SECTION D**

Super Jumbo Tex 60, water resistant barrier applied over Tyvek Commercial wrap.

PHOTOGRAPH #16



**BUILDING 2
SECTION D**

Electrical and A/C penetrations have not been detailed with Tyvek Flex Wrap (as required by manufacture) prior to cover with Super Jumbo Tex 60.

PHOTOGRAPH #17



**BUILDING 2
SECTION D**

Roofing sheathing deteriorated at several soffit locations.

PHOTOGRAPH #18



**BUILDING 2
SECTION C**

Weep screed at wall base applied and flashed with Dupont flashing.

PHOTOGRAPH #19



**BUILDING 1
UNIT #125 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #20



**BUILDING 1
UNIT #125 – ATTIC**

Gusset, scabs, and fire wall repairs performed and quantified.

PHOTOGRAPH #21



**BUILDING 2
SECTION B**

New PGT windows installed with DuPont flashing details and Tyvek CommercialWrap.

PHOTOGRAPH #22



**BUILDING 2
SECTION B**

Tyvek CommercialWrap WRB negatively overlapped at balcony columns.

PHOTOGRAPH #23



**BUILDING 2
SECTION A**

Window installations inspected for proper gaps and flashing overlaps per manufacturers specifications and NOAs.

PHOTOGRAPH #24



**BUILDING 2
SECTION A**

Window installations inspected for proper gaps and flashing overlaps per manufacturers specifications and NOAs.

PHOTOGRAPH #25



**BUILDING 2
SECTION A**

15/32" plywood sheathing applied.
Existing windows temporarily reinstalled.

PHOTOGRAPH #26



**BUILDING 2
SECTION A**

New PGT windows installed with DuPont
flashing details and Tyvek
CommercialWrap.