

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 1
SECTION F**

Balcony handrail attachment angels have been welded to railing and fasted through stucco into framing.

PHOTOGRAPH #2



**BUILDING 1
SECTION F**

Balcony handrail attachment angels have been welded to railing and fasted through stucco into framing.

PHOTOGRAPH #3



**BUILDING 1
SECTION F - UNIT #126**

Interior drywall repairs and finish at window openings in progress.

PHOTOGRAPH #4



**BUILDING 1
SECTION C**

Backing rod and new sealants installed at window perimeter with BASF 150 sealant.

PHOTOGRAPH #5



**BUILDING 1
SECTION C**

Backing rod and new sealants installed at window perimeter with BASF 150 sealant.

PHOTOGRAPH #6



**BUILDING 1
SECTION C - UNIT #128**

Interior drywall and sill repairs at window openings in progress.

PHOTOGRAPH #7



**BUILDING 1
SECTION A**

Florida Paints Ultra Exterior Super Coat applied at new stucco surfaces.

PHOTOGRAPH #8



**BUILDING 2
SECTION H**

Dupont/Tyvek flashing details have been completed per manufacturers instruction and AAMA/FMA guidelines.

PHOTOGRAPH #9



**BUILDING 2
SECTION G**

Bora Care Terminate treatment applied by pest contractor to wood framing prior to new sheathing.

PHOTOGRAPH #10



**BUILDING 2
SECTION G**

Contractor in process of installing new plywood sheathing.

PHOTOGRAPH #11



**BUILDING 2
SECTION G**

New pressure treated 15/32 " sheathing installed at bottom row of wall.

PHOTOGRAPH #12



**BUILDING 2
SECTION G**

BASF urethane sealants installed at bottom plate to concrete slab.

PHOTOGRAPH #13



**BUILDING 2
SECTION E**

Simpson Strong-Tie strapping, connectors, and screws installation in progress at second floor headers, top plate, and studs.

PHOTOGRAPH #14



**BUILDING 2
SECTION E**

Missing Simpson Strong-Tie Titen anchor at breezeway base plate.

PHOTOGRAPH #15



**BUILDING 2
SECTION D**

Framing damage marked for repairs at window headers, studs, and bottom plates of second floor.

PHOTOGRAPH #16



**BUILDING 2
SECTION D**

Framing damage marked for repairs at window headers, studs, and bottom plates of second floor.

PHOTOGRAPH #17



**BUILDING 2
SECTION D**

Damage marked for repairs at gable end trusses and second floor top plate.

PHOTOGRAPH #18



**BUILDING 2
SECTION D**

Contractor performing reinforcement repairs at gable end trusses.

PHOTOGRAPH #19



**BUILDING 2
SECTION A**

Contractor has removed stucco and Thermo-Ply exposing damage and wood repairs.