

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 6 SECTION A-D

Framing repairs completed. Contractor to start Simpson connector and strap installation.

PHOTOGRAPH #2



BUILDING 6 SECTION A-D

Framing repairs completed. Contractor to start Simpson connector and strap installation.

PHOTOGRAPH #3



**BUILDING 6
SECTION D**

Simpson Strong Tie connector straps types D and E were installed with 10d nails per drawings and specifications.

PHOTOGRAPH #4



**BUILDING 6
SECTION D**

Simpson Strong Tie connector straps types D and E were installed with 10d nails per drawings and specifications.

PHOTOGRAPH #5



**BUILDING 6
SECTION G**

Simpson Strong Tie connector straps types D and E were installed with 10d nails per drawings and specifications.

PHOTOGRAPH #6



**BUILDING 6
SECTION D**

Contractor is preparing to install Simpson Strong Tie connectors to bottom plate.

PHOTOGRAPH #7



**BUILDING 6
SECTION F**

1x12 rough sawn cedar trim board was attached to balcony edge per drawings and specifications.

PHOTOGRAPH #8



**BUILDING 6
SECTION F**

1x12 rough sawn cedar trim board was attached to balcony edge per drawings and specifications.

PHOTOGRAPH #9



**BUILDING 6
SECTION G**

Contractor to apply MasterSeal 150 sealant around windows.

PHOTOGRAPH #10



**BUILDING 6
SECTION H**

MasterSeal 150 sealant was applied around windows.

PHOTOGRAPH #11



**BUILDING 6
SECTION H**

Contractor applied a bead of MasterSeal 150 sealant and did not tool flush.

Contractor to remove, reapply, and tool sealant per manufacturer's instructions.

PHOTOGRAPH #12



**BUILDING 3
SECTION A-H**

The exterior of Building 3 was reviewed for completion with contractor.

PHOTOGRAPH #13



**BUILDING 3
SECTION A**

Trim and touch-up at bottom of breezeway column.

PHOTOGRAPH #14



**BUILDING 3
SECTION B**

Opening at window trim to be sealed.

PHOTOGRAPH #15



**BUILDING 3
SECTION C**

Gaps located at the top of breezeway.
Contractor to seal gaps.

PHOTOGRAPH #16



**BUILDING 3
SECTION D**

Missing light fixture. Contractor to install.

PHOTOGRAPH #17



**BUILDING 3
SECTION H**

Wall penetration is missing sealant.
Contractor to apply sealant.