

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 6 SECTION A

Sub-contractor has applied three coat 7/8" stucco system as per specifications.

PHOTOGRAPH #2



BUILDING 6 SECTION A

Contractor has begun to apply BASF Masterseal 150 Hybrid sealant at windows.


PHOTOGRAPH #3



**BUILDING 6
SECTION A**

Contractor preparing to apply Masterseal NP 150 at wind perimeters.

PHOTOGRAPH #4



**BUILDING 6
SECTION A**

Repair materials and equipment moved out of walk path and safety cones placed for pedestrian awareness.

PHOTOGRAPH #5



**BUILDING 6
SECTION B**

Sub-contractor has applied three coat 7/8" stucco system as per specifications.

PHOTOGRAPH #6



**BUILDING 6
SECTION C**

Sub-contractor has protected windows and applied scratch coat of stucco as per specifications.

PHOTOGRAPH #7



**BUILDING 6
SECTION C**

Unit #617- Drywall repairs and texture in progress at new windows.

PHOTOGRAPH #8



**BUILDING 6
SECTION D**

Sub-contractor has installed vinyl stucco accessories and metal lathing for application of new stucco.


PHOTOGRAPH #9



**BUILDING 6
SECTION D**

Stucco accessories at head of new windows provides weep screed holes through stucco stop as per drawings and specifications.

PHOTOGRAPH #10



**BUILDING 6
SECTION D**

Metal lathing overlaps meet minimum requirements per ASTM and PM specifications.

PHOTOGRAPH #11



**BUILDING 6
SECTION D**

New wood soffit at gable end wall installed and painted prior to application of new stucco.

PHOTOGRAPH #12



**BUILDING 6
SECTION E**

Steel balcony railings have been repainted and re attached to balcony built up beams with 3/8" x 4" galvanized lag screws.

PHOTOGRAPH #13



**BUILDING 6
SECTION E**

Steel balcony railings have been repainted and re attached to balcony built up beams with 3/8" x 4" galvanized lag screw.

PHOTOGRAPH #14



**BUILDING 6
SECTION E**

Stairway railing finish coated with Florida Paints High-Performance two-part urethane enamel.


PHOTOGRAPH #15



**BUILDING 6
SECTION E**

Stairway railing finish coated with Florida Paints High-Performance two-part urethane enamel.

PHOTOGRAPH #16



**BUILDING 6
SECTION G**

Unit #624- Interior sealant detail and drywall repairs in progress at new windows.

PHOTOGRAPH #17



**BUILDING 6
SECTION G**

Unit #624- Interior sealant applied from new window to Dupont FlexWrap as per drawings and manufacturers requirements.