

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 7 SECTION H

Exterior walls removed for inspection and marking of wood repairs required.

PHOTOGRAPH #2



BUILDING 7 SECTION H

Damaged framing marked for repairs at window framing, jacks, and plates.

PHOTOGRAPH #3



**BUILDING 7
SECTION H**

Damaged double window headers marked for replacement.

PHOTOGRAPH #4



**BUILDING 7
SECTION H**

Damaged roof truss marked for repair at gable end wall.

PHOTOGRAPH #5



**BUILDING 7
SECTION H**

Previous and current leaks have damaged roof sheathing. Owners to have repairs done by others.

PHOTOGRAPH #6



**BUILDING 7
SECTION H**

Contractor's erection and inspection tag (requiring inspection and competent persons approval before scaffolding is use) is in place.

PHOTOGRAPH #7



**BUILDING 7
SECTION G**

Exterior walls removed for inspection and marking of wood repairs required.

PHOTOGRAPH #8



**BUILDING 7
SECTION G**

Damaged framing marked for repairs at window framing and jacks.

PHOTOGRAPH #9



**BUILDING 7
SECTION G**

Breezeway beam damaged by wood rot and termites marked for replacement.

PHOTOGRAPH #10



**BUILDING 7
SECTION F**

Damaged framing marked for repairs at window framing, jacks, and plates.

PHOTOGRAPH #11



**BUILDING 7
SECTION F**

Wood framing studs damaged by wood rot and termites marked for replacement.

PHOTOGRAPH #12



**BUILDING 7
SECTION F**

Unit #726- Owners have covered wood decking at balcony with additional decking.

PHOTOGRAPH #13



**BUILDING 7
SECTION E**

Exterior walls removed for inspection and marking of wood repairs required.

PHOTOGRAPH #14



**BUILDING 7
SECTION E**

Breezeway beam damaged termites marked for replacement.

PHOTOGRAPH #15



**BUILDING 7
SECTION E**

Damaged single window header marked for replacement.