

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 6
SECTION F**

Contractor installing new bronze aluminum screen enclosures where previously existed at owner's lanai (typical).

PHOTOGRAPH #2



**BUILDING 6
SECTION F**

New aluminum screen enclosure fastened at concrete slab with stainless steel fasteners and sealed with BASF urethane sealant. Angle bracing attached to framing trough stucco at vertical post (typical).

PHOTOGRAPH #3



**BUILDING 6
SECTION F**

New aluminum screen enclosure fastened at concrete slab with stainless steel fasteners and sealed with BASF urethane sealant (typical).

PHOTOGRAPH #4



**BUILDING 6
SECTION G**

Contractor installed brackets to attach balcony railing to walls (typical).

PHOTOGRAPH #5



**BUILDING 6
SECTION G**

Contractor installed brackets to attach balcony railing to walls (typical).

PHOTOGRAPH #6



**BUILDING 3
SECTION C**

Sub-Contractor welding new steel support angle under three new stair pads and marked for repairs.

PHOTOGRAPH #7



**BUILDING 3
SECTION C**

Sub-Contractor welding new steel support angle under three new stair pads and marked for repairs.

PHOTOGRAPH #8



**BUILDING 3
SECTION C**

Sub-Contractor welding new steel angles support under three new stair pads and marked for repairs.