

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 6
UNIT 621 - ATTIC**

Contractor has performed truss scab repairs and gusset plate repairs.

PHOTOGRAPH #2



**BUILDING 6
UNIT 621 - ATTIC**

Contractor has performed truss scab repairs.

Larger gusset plate is needed with more screws, as per the drawings. Reported to contractor.

PHOTOGRAPH #3



**BUILDING 6
UNIT 621 - ATTIC**

Wood Construction Screw used for truss scab repairs.

PHOTOGRAPH #4



**BUILDING 6
UNIT 621 - ATTIC**

Contractor installing Liquid Nails for gusset plate repairs.

PHOTOGRAPH #5



**BUILDING 6
UNIT 621 - ATTIC**

Liquid Nails used for gusset plate repairs.

PHOTOGRAPH #6



**BUILDING 6
UNIT 621 - ATTIC**

Contractor has performed gusset plate repairs.

PHOTOGRAPH #7



**BUILDING 6
UNIT 621 - ATTIC**

Recently found damaged truss member.
Contractor to perform truss scab repairs.

PHOTOGRAPH #8



**BUILDING 6
UNIT 621 - ATTIC**

Recently found damaged truss member.
Contractor to perform truss scab repairs.

PHOTOGRAPH #9



**BUILDING 6
UNIT 621 - ATTIC**

Contractor has performed truss scab repairs on recently found damaged truss member.

PHOTOGRAPH #10



**BUILDING 6
UNIT 623 - ATTIC**

3M Fire Barrier sealant applied at fire wall penetrations and fire wall repairs.


PHOTOGRAPH #11



**BUILDING 6
UNIT 623 - ATTIC**

3M Fire Barrier sealant applied at fire wall penetrations and fire wall repairs.

PHOTOGRAPH #12



**BUILDING 6
UNIT 623 - ATTIC**

3M Fire Barrier sealant applied at fire wall penetrations and fire wall repairs.

Fire wall repair incomplete around wooden beam in fire wall. Reported to Contractor.

PHOTOGRAPH #13



**BUILDING 6
UNIT 623 - ATTIC**

Screws were added to fire wall repair to conform with 6" on-center spacing requirement.

PHOTOGRAPH #14



**BUILDING 6
UNIT 623 - ATTIC**

Larger gusset plate is needed with more screws, as per the drawings. Reported to contractor.


PHOTOGRAPH #15



**BUILDING 6
UNIT 623 - ATTIC**

Contractor installing Liquid Nails for gusset plate repairs.

PHOTOGRAPH #16



**BUILDING 6
UNIT 623 - ATTIC**

Contractor has performed gusset plate repairs in the location that required a larger gusset plate.


PHOTOGRAPH #17



**BUILDING 6
UNIT 625 - ATTIC**

3M Fire Barrier sealant applied at fire wall repairs.

PHOTOGRAPH #18



**BUILDING 6
UNIT 625 - ATTIC**

3M Fire Barrier sealant applied at fire wall repairs.


PHOTOGRAPH #19



**BUILDING 6
UNIT 625 - ATTIC**

3M Fire Barrier sealant applied at fire wall repairs.


PHOTOGRAPH #20



**BUILDING 6
UNIT 626 - ATTIC**

3M Fire Barrier sealant applied at fire wall repairs.

PHOTOGRAPH #21



**BUILDING 6
UNIT 626 - ATTIC**

Contractor has performed truss scab repairs.

PHOTOGRAPH #22



**BUILDING 6
UNIT 626 - ATTIC**

Contractor has performed truss scab repairs.

PHOTOGRAPH #23



**BUILDING 6
UNIT 626 - ATTIC**

Contractor has performed gusset plate repairs.

PHOTOGRAPH #24



**BUILDING 6
UNIT 627 - ATTIC**

Contractor has performed truss scab repairs.

PHOTOGRAPH #25



**BUILDING 6
UNIT 627 - ATTIC**

Larger gusset plate is needed with more screws, as per the drawings. Reported to contractor.

PHOTOGRAPH #26



**BUILDING 6
UNIT 628 - ATTIC**

Contractor has performed truss scab repairs.