

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 6 SECTION B

Contractor installing new bronze aluminum screen enclosures where previously existed at owners lanai.

PHOTOGRAPH #2



BUILDING 6 SECTION B

New aluminum screen enclosure fastened at concrete slab with 3" stainless steel fasteners and sealed with BASF urethane sealant.


PHOTOGRAPH #3



**BUILDING 6
SECTION B**

New aluminum screen enclosure fastened at concrete slab with 3" stainless steel fasteners and sealed with BASF urethane sealant.

PHOTOGRAPH #4



**BUILDING 6
SECTION B**

Contractor installing new screen at new enclosure.

PHOTOGRAPH #5



**BUILDING 6
SECTION E**

Stucco patching at breezeway wall.

PHOTOGRAPH #6



**BUILDING 6
SECTION F**

Contractor installing new bronze aluminum screen enclosures where previously existed at owners lanai.

PHOTOGRAPH #7



**BUILDING 6
SECTION F**

Contractor has removed and replaced window perimeter sealant where plastic was attached to sealants.