

PHOTOGRAPHS


PHOTOGRAPH #1



**BUILDING 7
SECTION A- BREEZEWAY**

Contractor has spray painted steel stairway railing with Florida Paints Sundeavor Urethane Enamel.

PHOTOGRAPH #2



**BUILDING 7
SECTION A- BREEZEWAY**

Contractor has spray painted steel stairway railing with Florida Paints Sundeavor Urethane Enamel.

PHOTOGRAPH #3



**BUILDING 7
SECTION A**

Contractor painting concrete stair pads at breezeway stairways with Florida Paints TropiCrete Concrete Sealer.

PHOTOGRAPH #4



**BUILDING 7
SECTION A**

Contractor painting concrete stair pads at breezeway stairways with Florida Paints TropiCrete Concrete Sealer.

PHOTOGRAPH #5



**BUILDING 7
SECTION A- BREEZEWAY**

Steel railings at balconies have been attached at top railing through stucco into framing at welded brackets with anchor bolts.

PHOTOGRAPH #6



**BUILDING 7
SECTION C**

Contractor has spray painted steel stairway railing with Florida Paints Sundeavor Urethane Enamel.

PHOTOGRAPH #7



**BUILDING 7
SECTION F**

Unit #724- Truss scab repairs performed in attic space as per drawings.

PHOTOGRAPH #8



**BUILDING 7
SECTION F**

Unit #724- Gusset plate repair details performed in attic space as per drawings.

PHOTOGRAPH #9



**BUILDING 7
SECTION F**

Unit # 724- Fire board repairs and fire caulk repairs performed in attic space.

PHOTOGRAPH #10



**BUILDING 8
SECTION F**

Sub-Contractor has applied three coat 7/8" stucco system as per specifications and ASTM standards.

PHOTOGRAPH #11



**BUILDING 8
SECTION E**

Sub-Contractor has applied three coat 7/8" stucco system as per specifications and ASTM standards.

PHOTOGRAPH #12



**BUILDING 8
SECTION D**

Gable end wall plastic tarp protection has been secured over open space at attic.

PHOTOGRAPH #13



**BUILDING 8
SECTION C**

Contractor replacing damaged breezeway framing as marked for repairs.

PHOTOGRAPH #14



**BUILDING 8
SECTION B**

Unit #825- contractor has replaced built up beam at balcony as per drawings.

PHOTOGRAPH #15



**BUILDING 8
SECTION A**

Contractor replacing damaged breezeway framing as marked for repairs.

PHOTOGRAPH #16



**BUILDING 8
GROUNDS**

New PGT windows delivered to site have been left outside of storage trailer.

PHOTOGRAPH #17



**BUILDING 8
GROUNDS**

Stucco staging area is outside of construction fencing and sand is not covered.

PHOTOGRAPH #18



**BUILDING 13
SECTION H**

Open walls have been covered with heavy duty plastic protection.

PHOTOGRAPH #19



**BUILDING 13
SECTION F**

Open walls have been covered with heavy duty plastic protection.

PHOTOGRAPH #20



**BUILDING 13
SECTION A**

Breezeway stairway railings are in process of preparation by grinding away loose paint and rust.