

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 7
SECTION A- BREEZEWAY**

Floor paint appears to have been damaged by rain prior to drying.

PHOTOGRAPH #2



**BUILDING 7
SECTION A- ATTIC**

Unit #721- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #3



**BUILDING 7
SECTION A-ATTIC**

Unit #721- Contractor has performed scab repairs at trusses as per drawings in attic.


PHOTOGRAPH #4



**BUILDING 7
SECTION A-ATTIC**

Unit # 721- Contractor has performed scab repairs at trusses as per drawings in attic.

PHOTOGRAPH #5



**BUILDING 7
SECTION A- ATTIC**

Unit # 721- Contractor has performed fire wall repairs at separation wall as per drawings in attic.


PHOTOGRAPH #6



**BUILDING 7
SECTION B- ATTICS**

Unit #725- Contractor has performed scab repairs at trusses as per drawings in attic.

PHOTOGRAPH #7



**BUILDING 7
SECTION B- ATTICS**

Unit #725- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #8



**BUILDING 7
SECTION B- ATTICS**

Unit #725- Fire caulk repairs performed in attic space at penetrations and holes.

PHOTOGRAPH #9



**BUILDING 7
SECTION C- ATTICS**

Unit # 727- Contractor has performed scab repairs at trusses as per drawings in attic.

PHOTOGRAPH #10



**BUILDING 7
SECTION C- ATTICS**

Unit # 727- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #11



**BUILDING 7
SECTION C- ATTICS**

Unit # 727- Fire caulk repairs performed in attic space at penetrations and holes.

PHOTOGRAPH #12



**BUILDING 7
SECTION E-ATTICS**

Unit #728- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #13



**BUILDING 7
SECTION E-ATTICS**

Unit #728- Contractor has performed fire wall repairs at separation wall as per drawings in attic.

PHOTOGRAPH #14



**BUILDING 7
SECTION E-ATTICS**

Unit #728- Contractor has performed scab repairs at trusses as per drawings in attic.

PHOTOGRAPH #15



**BUILDING 7
SECTION F-ATTICS**

Unit #726- Contractor has performed scab repairs at trusses as per drawings in attic.

PHOTOGRAPH #16



**BUILDING 7
SECTION F-ATTICS**

Unit #726- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #17



**BUILDING 7
SECTION F-ATTICS**

Unit #726- Contractor has performed fire wall repairs at separation wall as per drawings in attic.

PHOTOGRAPH #18



**BUILDING 8
SECTION F**

Handrailing brackets at top railing have been painted.

PHOTOGRAPH #19



**BUILDING 7
SECTION H-ATTICS**

Unit #722- Contractor has performed gusset repairs at trusses as per drawings in attic.

PHOTOGRAPH #20



**BUILDING 7
SECTION H-ATTICS**

Unit #722- Contractor has performed fire wall repairs at separation wall as per drawings in attic.

PHOTOGRAPH #21



**BUILDING 8
SECTION -GROUNDS AREA**

Construction fencing has been secured around stucco staging area.

PHOTOGRAPH #22



**BUILDING 8
SECTION H**

Contractor has protected new windows and applied Florida Paint acrylic masonry primer to new stucco.

PHOTOGRAPH #23



**BUILDING 8
SECTION H**

Contractor has applied Florida Paint Ultra Exterior SuperCoat over acrylic masonry primer at new stucco.

PHOTOGRAPH #24



**BUILDING 8
SECTION G**

Contractor has protected new windows and applied Florida Paint acrylic masonry primer to new stucco.

PHOTOGRAPH #25



**BUILDING 8
SECTION F**

Contractor masking metal frames and installing MasterSeal NP 150 sealant at new window perimeters.

PHOTOGRAPH #26



**BUILDING 8
SECTION F**

Contractor masking metal frames and installing MasterSeal NP 150 sealant at new window perimeters.

PHOTOGRAPH #27



**BUILDING 8
SECTION D**

Bora-Care Termite treatment applied to framing and New Simpson Strong-Tie connectors installed as per drawings.

PHOTOGRAPH #28



**BUILDING 8
SECTION D**

Contractor has begun placing new pressure treated plywood sheathing at bottom row as per specifications.

PHOTOGRAPH #29



**BUILDING 8
SECTION H**

New R-19 insulation installed where damaged or missing.

PHOTOGRAPH #30



**BUILDING 8
SECTION H**

New Owens Corning R-19 insulation installed where damaged or missing.

PHOTOGRAPH #31



**BUILDING 13
SECTION H**

Contractor has begun framing repairs at top plate and windows of gable end wall.