

PHOTOGRAPHS

PHOTOGRAPH #1



**BUILDING 13  
SECTION H**

Stucco sub-contractor applying finish coat of three coat 7/8" stucco as per drawings and specification .

PHOTOGRAPH #2



**BUILDING 13  
SECTION H**

Stucco sub-contractor applying finish coat of three coat 7/8" stucco as per drawings and specification.

**PHOTOGRAPH #3**



**BUILDING 13  
SECTION G**

Stucco sub-contractor applying scratch coat of three coat 7/8" stucco as per drawings and specification.

**PHOTOGRAPH #4**



**BUILDING 13  
SECTION F**

Stucco sub-contractor applying scratch coat of three coat 7/8" stucco as per drawings and specification.

**PHOTOGRAPH #5**



**BUILDING 13  
SECTION F**

Stucco sub-contractor has protected adjacent surfaces at balcony with protection sheet.

**PHOTOGRAPH #6**



**BUILDING 13  
SECTION D**

RLJ has installed new 15/32" plywood sheathing per drawing and specifications.

**PHOTOGRAPH #7**



**BUILDING 13  
SECTION D**

New Green Heck louvers installation in progress at gable end attic space as per specifications.

**PHOTOGRAPH #8**



**BUILDING 13  
SECTION D**

RLJ has installed Tyvek Home wrap water resistant barrier at gable end wall.

**PHOTOGRAPH #9**



**BUILDING 13  
SECTION C**

RLJ has fastened new plywood sheathing to framing member were missed and marked by Delta for correction.

**PHOTOGRAPH #10**



**BUILDING 13  
SECTION C**

RLJ has installed Tyvek Home wrap water resistant barrier at framed bearing walls.

**PHOTOGRAPH #11**



**BUILDING 13  
SECTION C**

DuPont Tyvek manufacturer's representative on site, inspecting Tyvek installation.


**PHOTOGRAPH #12**



**BUILDING 13  
SECTION B**

RLJ in process of installing 15/32" plywood sheathing.

**PHOTOGRAPH #13**



**BUILDING 13  
SECTION B**

New plywood sheathing attached to framing members at 16" spacing as per drawings and specifications.

**PHOTOGRAPH #14**



**BUILDING 13  
SECTION B**

New plywood sheathing attached to framing members with 10d nails at 4" O.C.

**PHOTOGRAPH #15**



**BUILDING 18  
SECTION H**

RLJ has protected open walls with heavy duty plastic while repairs are in progress.

**PHOTOGRAPH #16**



**BUILDING 13  
SECTION F**

RLJ has protected open walls with heavy duty plastic while repairs are in progress.

**PHOTOGRAPH #17**



**BUILDING 18  
SECTION F**

Upper balconies covered with carpet by owners will require removal for inspection of deck condition.