

**PHOTOGRAPH #1**



**BUILDING 13  
SECTION F**

Several windows have stucco filling head flashing that needs to remain open for function of weep detail.

**PHOTOGRAPH #2**



**BUILDING 13  
SECTION F - UNIT 1316**

Interior bead of sealant installed from window frame to Tyvek flashings as per drawings and new drywall installation in progress.

**PHOTOGRAPH #3**



**BUILDING 13  
SECTION B**

Cedar cover boards have not yet been applied to new built-up beam repairs at upper balconies.

**PHOTOGRAPH #4**



**BUILDING 13  
SECTION B**

Clean up of stucco and construction debris in progress.

**PHOTOGRAPH #5**



**BUILDING 13  
SECTION A**

Gas pipe penetration through stucco wall has not yet been sealed as per specifications.

**PHOTOGRAPH #6**



**BUILDING 13  
SECTION A**

Stucco and construction debris has been cleaned up in this area.

**PHOTOGRAPH #7**



**BUILDING 18  
SECTION F**

New vinyl stucco accessories and joints fastened to framing at no more than 7" intervals and new sealants installed at butts and corners.

**PHOTOGRAPH #8**



**BUILDING 18  
SECTION F**

New vinyl stucco accessories and joints fastened to framing at no more than 7" intervals and new sealants installed at butts and corners.

**PHOTOGRAPH #9**



**BUILDING 18  
SECTION F**

RLJ installing new kick out flashings at upper balconies as per drawings and specifications.

**PHOTOGRAPH #10**



**BUILDING 18  
SECTION F**

RLJ installing new kick out flashing details at roof locations per drawings and specifications before roof tile is reinstalled.


**PHOTOGRAPH #11**



**BUILDING 18  
SECTION E**

New sealants installed at base plate to foundation slab and base plate to new plywood sheathing as per drawings.

**PHOTOGRAPH #12**



**BUILDING 18  
SECTION E**

New plywood soffit and vinyl venting installed to replace existing as per drawings.

**PHOTOGRAPH #13**



**BUILDING 18  
SECTION D**

Pest contractor has applied Bora care termite treatment to gable end wall.

**PHOTOGRAPH #14**



**BUILDING 18  
SECTION B**

Existing roof sheathing has been damaged by leaks and is to be repaired by owners' contractors.

**PHOTOGRAPH #15**



**BUILDING 18  
SECTION B**

Existing roof sheathing has been damaged by leaks and is to be repaired by owners' contractors.

**PHOTOGRAPH #16**



**BUILDING 18  
SECTION E**

Existing roof sheathing has been damaged by leaks and is to be repaired by owners' contractors.