

**PHOTOGRAPH #1**



**BUILDING 13  
SECTION H- UNIT #1321**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.

**PHOTOGRAPH #2**



**BUILDING 13  
SECTION H- UNIT #1321**

Contractor has performed gusset repairs in attic at truss connections as per drawings.

**PHOTOGRAPH #3**



**BUILDING 13  
SECTION H- UNIT #1321**

Contractor has performed fire board repairs in attic as per specifications.

**PHOTOGRAPH #4**



**BUILDING 13  
SECTION H- UNIT #1322**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.


**PHOTOGRAPH #5**



**BUILDING 13  
SECTION H- UNIT #1322**

Contractor has performed fire caulk repairs in attic at fire walls as per drawings.

**PHOTOGRAPH #6**



**BUILDING 13  
SECTION G- BREZEWAY**

Contractor applying breezeway railing finish paint with conventional spray equipment.

**PHOTOGRAPH #7**



**BUILDING 13  
SECTION F**

Cedar cover boards have been applied to new built-up beam repairs at upper balconies.

**PHOTOGRAPH #8**



**BUILDING 13  
SECTION F-UNIT #1324**

Contractor has performed gusset repairs in attic at truss connections as per drawings.

**PHOTOGRAPH #9**



**BUILDING 13  
SECTION F-UNIT #1324**

Contractor has performed fire board repairs in attic at fire walls as per drawings.

**PHOTOGRAPH #10**



**BUILDING 13  
SECTION F-UNIT #1326**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.

**PHOTOGRAPH #11**



**BUILDING 13  
SECTION F-UNIT #1326**

Contractor has performed gusset repairs in attic at truss connections as per drawings.

**PHOTOGRAPH #12**



**BUILDING 13  
SECTION E- BREEZEWAY**

Contractor has finish painted breezeway railings and steps with Florida Paint coatings as per specifications.

**PHOTOGRAPH #13**



**BUILDING 13  
SECTION D- UNIT #1328**

Contractor has performed gusset repairs in attic at truss connections as per drawings.

**PHOTOGRAPH #14**



**BUILDING 13  
SECTION D- UNIT #1328**

Contractor has performed fire board repairs in attic at fire walls as per drawings.

**PHOTOGRAPH #15**



**BUILDING 13  
SECTION D- UNIT #1328**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.

**PHOTOGRAPH #16**



**BUILDING 13  
SECTION B- UNIT #1325**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.

**PHOTOGRAPH #17**



**BUILDING 13  
SECTION B- UNIT #1325**

Contractor has performed fire board repairs in attic at fire walls as per drawings.

**PHOTOGRAPH #18**



**BUILDING 13  
SECTION B- UNIT #1323**

Contractor has performed gusset repairs in attic at truss connections as per drawings.


**PHOTOGRAPH #19**



**BUILDING 13  
SECTION B- UNIT #1323**

Contractor has performed scab repairs in attic at damaged trusses as per drawings.

**PHOTOGRAPH #20**



**BUILDING 13  
SECTION A- BREEZEWAY**

Contractor has primed breezeway railings with Florida Paints Encapsulon Epoxy mastic primer.


**PHOTOGRAPH #21**



**BUILDING 18  
SECTION F**

Stucco sub-contractors have installed galvanized lath and new vinyl stucco accessories.

**PHOTOGRAPH #22**



**BUILDING 18  
SECTION F**

Overlapping galvanized lathing is tied between framing studs with SS wire at intervals no more than 9" O.C.

**PHOTOGRAPH #23**



**BUILDING 18  
SECTION D**

Gable end covered with Dupont Tyvek water resistant barrier.

**PHOTOGRAPH #24**



**BUILDING 18  
SECTION C**

Simpsons Strong Tie connector straps installed from framing studs to framing studs first to second level as per drawings.

**PHOTOGRAPH #25**



**BUILDING 18  
SECTION C**

Additional damaged framing marked for repairs at breezeway wall.

**PHOTOGRAPH #26**



**BUILDING 18  
SECTION A**

Additional damaged top plate framing marked for repairs. Stucco will need to be removed to end of damage for repairs.

**PHOTOGRAPH #27**



**BUILDING 8  
SECTION B**

Screen enclosure installation in progress  
at lower patio.

**PHOTOGRAPH #28**



**BUILDING 8  
SECTION C**

Screen enclosure installation in progress  
at lower patio.

**PHOTOGRAPH #29**



**BUILDING 8  
SECTION C**

Contractors remaining equipment and materials to be removed from grounds.