

PHOTOGRAPH #1



**BUILDING 18
SECTION A**

Stucco sub-contractor has completed final finish coat stucco.

PHOTOGRAPH #2



**BUILDING 18
SECTION A**

New NP 150 BASF sealants applied at stucco transition joints .


PHOTOGRAPH #3



**BUILDING 18
SECTION A**

New NP 150 BASF sealants applied at stucco transition joints.

PHOTOGRAPH #4



**BUILDING 18
SECTION B**

Stairway railings prime coated with Florida Paints Encapsulon two-part epoxy.


PHOTOGRAPH #5



**BUILDING 18
SECTION B**

Contractor protecting windows with plastic covering prior to stucco paint applications.

PHOTOGRAPH #6



**BUILDING 18
SECTION B**

Contractor has applying finish coat of Florida Paint Glades Exterior Acrylic.


PHOTOGRAPH #7



**BUILDING 18
SECTION C**

Contractor has applying finish coat of Florida Paint Glades Exterior Acrylic.

PHOTOGRAPH #8



**BUILDING 18
SECTION C**

Contractor priming stairway railings with Florida Paints Encapsulon two-part epoxy.

PHOTOGRAPH #9



**BUILDING 18
SECTION C**

Contractor priming stairway railings with Florida Paints Encapsulon two-part epoxy.

PHOTOGRAPH #10



**BUILDING 18
UNIT #1821- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #11



**BUILDING 18
UNIT #1821- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #12



**BUILDING 18
UNIT #1823- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #13



**BUILDING 18
UNIT #1823- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #14



**BUILDING 18
UNIT #1826- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #15



**BUILDING 18
UNIT #1826- ATTIC**

Contractor has repaired damaged attic fire wall with fire board repair detail as per project drawings.

PHOTOGRAPH #16



**BUILDING 18
UNIT #1826- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #17



**BUILDING 18
UNIT #1827- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #18



**BUILDING 18
UNIT #1827- ATTIC**

Contractor has repaired damaged attic fire wall with fire board repair detail as per project drawings.

PHOTOGRAPH #19



**BUILDING 18
UNIT #1827- ATTIC**

Fire barrier sealant applied at fire wall penetrations and new fire wall perimeters.

PHOTOGRAPH #20



**BUILDING 18
UNIT #1827- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #21



**BUILDING 18
UNIT #1825- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #22



**BUILDING 18
UNIT #1825- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.