


PHOTOGRAPH #1



**BUILDING 18
SECTION C**

Contractor priming and painting cedar facing at balconies built up beams.

PHOTOGRAPH #2



**BUILDING 18
SECTION G**

Contractor has applied Florida Paints urethane aliphatic gloss enamel paint.

PHOTOGRAPH #3



**BUILDING 18
UNIT #1822- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #4



**BUILDING 18
UNIT #1822- ATTIC**

Contractor has repaired damaged attic fire wall with new fire board repair.

PHOTOGRAPH #5



**BUILDING 18
UNIT #1822- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #6



**BUILDING 18
UNIT #1824- ATTIC**

Fire barrier sealant applied at fire wall penetrations and new fire wall perimeters.

PHOTOGRAPH #7



**BUILDING 18
UNIT #1824- ATTIC**

Contractor has repaired damaged attic truss with scab repair detail as per project drawings.

PHOTOGRAPH #8



**BUILDING 18
UNIT #1828- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.

PHOTOGRAPH #9



**BUILDING 18
UNIT #1828- ATTIC**

Contractor has repaired damaged attic fire wall with new fire board repair.

PHOTOGRAPH #10



**BUILDING 18
UNIT #1828- ATTIC**

Contractor has repaired damaged attic truss with gusset repair detail as per project drawings.