

PHOTOGRAPH #1



**BUILDING 18
SECTION A**

Contractor equipment, materials and debris remaining in front of building.

PHOTOGRAPH #2



**BUILDING 18
SECTION B**

Contractor has replaced patio screen enclosure. Balcony railing has not been re installed.


PHOTOGRAPH #3



**BUILDING 18
SECTION B**

Contractor equipment, materials and debris remaining in front of building.

PHOTOGRAPH #4



**BUILDING 18
SECTION B**

Dryer vents have yet to be replaced, sealed, and painted.

PHOTOGRAPH #5



**BUILDING 18
SECTION C**

Contractor has begun to install new patio screen enclosure. Balcony railing has not been re installed.

PHOTOGRAPH #6



**BUILDING 18
SECTION E**

Contractor has replaced patio screen enclosure. Balcony railing has not been re installed

PHOTOGRAPH #7



**BUILDING 18
SECTION F**

Contractor has replaced patio screen enclosure. Balcony railing has not been re installed.

PHOTOGRAPH #8



**BUILDING 18
SECTION G**

Balcony railing primed with Florida Paint Encapsulon epoxy mastic primer.


PHOTOGRAPH #9



**BUILDING 18
SECTION G**

Contractor painting balcony railings with Florida Paints Encapsulon epoxy mastic primer.

PHOTOGRAPH #10



**BUILDING 18
SECTION G**

Contractor painting balcony railings with Florida Paints Encapsulon epoxy mastic primer.