

PHOTOGRAPH #1



**BUILDING 11
SECTION B**

Pressure treated repair lumber staged in construction area.

PHOTOGRAPH #2



**BUILDING 11
SECTION B**

Pressure treated repair lumber staged in construction area.

PHOTOGRAPH #3



**BUILDING 11
SECTION H**

Gable end open for investigation and marking of framing repairs.

PHOTOGRAPH #4



**BUILDING 11
SECTION H**

Landscaping and grade level is above bottom plate and areas of wall framing. Removal and drainage will be required by owners as per drawings.

PHOTOGRAPH #5



**BUILDING 11
SECTION H**

Termite damage at window headers and window framing marked for repairs.

PHOTOGRAPH #6



**BUILDING 11
SECTION H**

Framing damage at floor truss, top plate and bottom plate marked for repairs.


PHOTOGRAPH #7



**BUILDING 11
SECTION H**

Window framing damage marked for repairs.

PHOTOGRAPH #8



**BUILDING 11
SECTION G**

Window framing damage marked for repairs.


PHOTOGRAPH #9



**BUILDING 11
SECTION G- UNIT #1122**

Damaged balcony deck boards marked to be removed and replaced.

PHOTOGRAPH #10



**BUILDING 11
SECTION F**

Bottom plate and wall framing damage marked for repairs.

PHOTOGRAPH #11



**BUILDING 11
SECTION F**

Window framing damage marked for repairs.

PHOTOGRAPH #12



**BUILDING 11
SECTION F- UNIT #1124**

Owners have covered balcony deck boards with tile.

PHOTOGRAPH #13



**BUILDING 11
SECTION F- UNIT #1126**

Damaged balcony decking and built-up beam marked for removal and replacement.

PHOTOGRAPH #14



**BUILDING 11
SECTION F**

Damage at window headers and window framing marked for repairs.

PHOTOGRAPH #15



**BUILDING 11
SECTION F**

Roof sheathing water damage to be repaired by owner's roof contractor.

PHOTOGRAPH #16



**BUILDING 11
SECTION E- UNIT #1128**

Upper balcony cedar header damaged by termites marked for removal and replacement.