

PHOTOGRAPH #1



**BUILDING 11
SECTION H**

Contractor has begun repairs at gable end wall framing.

PHOTOGRAPH #2



**BUILDING 11
SECTION H**

Repairs in place and quantified at gable wall framing studs , windows, headers, top plates, and bottom plates .

PHOTOGRAPH #3



**BUILDING 11
SECTION H**

Repairs in place and quantified at gable wall framing studs , windows, headers, top plates, and bottom plates .

PHOTOGRAPH #4



**BUILDING 11
SECTION G**

Damaged framing repairs in progress at balconies, windows, and wall studs as marked for repair.

PHOTOGRAPH #5



**BUILDING 11
SECTION F**

Damaged framing repairs in progress at balconies, windows, and wall studs as marked for repair.

PHOTOGRAPH #6



**BUILDING 11
SECTION F- UNIT #1126**

Contractor has performed full decking replacement and built-up beam repairs.

PHOTOGRAPH #7



**BUILDING 11
SECTION F- UNIT #1126**

Contractor has performed full decking replacement and built-up beam repairs.

PHOTOGRAPH #8



**BUILDING 11
SECTION F- UNIT #1124**

Contractor has removed balcony decking, built up beam and balcony trusses in preparation for repairs.

PHOTOGRAPH #9



**BUILDING 11
SECTION F**

Contractor has removed and replaced damaged triple header above triple windows.