


PHOTOGRAPH #1 A



**BUILDING 11
UNIT 1227 - WATER TEST**

Independent Testing Agency performed water infiltration testing at double windows in accordance with AAAMA 502. Testing failed with leak occurring at left windowsill.

PHOTOGRAPH #2 A



**BUILDING 11
UNIT 1227 - WATER TEST**

Independent Testing Agency performed water infiltration testing at double windows in accordance with AAAMA 502. Testing failed with leak occurring at left windowsill.

PHOTOGRAPH #3 A



**BUILDING 11
UNIT 1227 - WATER TEST**

Independent Testing Agency performed water infiltration testing at double windows in accordance with AAAMA 502. Testing failed with leak occurring at left windowsill.


PHOTOGRAPH #4 A



**BUILDING 11
UNIT 1227 - WATER TEST**

Independent Testing Agency performed water infiltration testing at single window in accordance with AAAMA 502. Testing passed with no leaks occurring.

PHOTOGRAPH #5 A



**BUILDING 11
UNIT 1227 - WATER TEST**

Independent Testing Agency performed water infiltration testing at single window in accordance with AAAMA 502. Testing passed with no leaks occurring.