

PHOTOGRAPHS

PHOTOGRAPH #1



BUILDING 20 SECTION B

New screen enclosure installed at patios.

PHOTOGRAPH #2



BUILDING 20 SECTION E

Florida Paints, Ultra Exterior Supercoat
100% acrylic applied to new stucco.

PHOTOGRAPH #3



**BUILDING 20
SECTION F**

Repainted railings being re installed at balconies.

PHOTOGRAPH #4



**BUILDING 20
SECTION F**

Railing attached to built-up beam with 4" lag bolts.

PHOTOGRAPH #5



**BUILDING 20
SECTION F**

Florida Paints, Ultra Exterior Supercoat
100% acrylic applied to new stucco.

PHOTOGRAPH #6



**BUILDING 20
SECTION G**

New screen enclosures being installed at
patios.